



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER
Colour	Silver
Year of manufacture	2013
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-25
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	4
Total items failed	4

MOT #11	2023-08-21 13:11
MOT test number	388407930169
Result	✓ Passed
Next expiry date	2024-09-07

MOT #10	2022-08-31 08:09
MOT test number	902290288718
Result	✓ Passed

MOT #9	2022-08-31 08:09
MOT test number	408420537487
Result	✗ Failed
Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #8	2021-09-08 13:06
MOT test number	720424056163
Result	✓ Passed

MOT #7	2020-09-07 12:16
MOT test number	564193906586
Result	✓ Passed

**MOT #6** 2020-09-03 13:40**MOT test number** 428844502102**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**MOT #5** 2019-09-19 14:35**MOT test number** 212891629745**Result** ✓ Passed**MOT #4** 2019-09-19 10:29**MOT test number** 735835244638**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #3** 2018-09-20 17:03**MOT test number** 431673639901**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre slightly damaged sidewall (5.2.3 (d) (ii))**MOT #2** 2017-10-10 15:04**MOT test number** 858407799252**Result** ✓ Passed



MOT #1	2016-09-14 15:21
MOT test number	690503037997
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-27
Last registration	2023-08-21
Complete history	See info



Registration #1	2013-09-27	9 mi
Registration #2	2016-09-14	27.985 mi
Registration #3	2017-10-10	38.824 mi
Registration #4	2018-09-20	49.540 mi
Registration #5	2019-09-19	59.409 mi
Registration #6	2019-09-19	59.409 mi
Registration #7	2020-09-03	62.312 mi
Registration #8	2020-09-03	62.312 mi
Registration #9	2020-09-03	62.312 mi
Registration #10	2020-09-03	62.312 mi
Registration #11	2020-09-03	62.312 mi
Registration #12	2020-09-03	62.312 mi
Registration #13	2020-09-03	62.312 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1384 mm
Length	3728 mm
Wheel base	2467 mm
Kerb weight	1120 kg
Max. allowed weight	1410 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2

Number of axles	2
Engine number	A978J560