



RENAULT

CW55F J0

report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC AUTHENTIQUE 16V G/SCENIC
Colour	Red
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-20
Pictures	2
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2021-12-20 11:09
MOT test number	374926536063
Result	✓ Passed
Next expiry date	2022-12-19
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2021-12-15 13:53
MOT test number	419921525550
Result	✗ Failed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
DANGEROUS	Front Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #17	2020-12-10 13:43
MOT test number	309706761599
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Rear Sound deadening material not fully secure (8.1.1 (b) (i))

MOT #16	2019-12-11 14:14
MOT test number	541661250206
Result	✓ Passed



MOT #15	2019-12-09 15:51
MOT test number	404188091977
Result	✗ Failed
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14	2018-12-10 17:10
MOT test number	953116750746
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13	2017-12-01 16:00
MOT test number	265575507088
Result	✓ Passed
Advice	Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)
Advice	Items removed from driver's view prior to test
Advice	Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened edge (3.5.1i)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12	2016-11-16 12:49
MOT test number	752777191675
Result	✓ Passed
Advice	Offside Rear tyre worn on edges and close to marker bars and some splitting due to age
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (3.5.1i)
Advice	Items removed from driver's view prior to test from mirror
Advice	Nearside Rear tyre worn on outer edge and close to marker bars
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rears (3.5.1i)

**MOT #11** 2015-11-18 13:45**MOT test number** 225321397468**Result** ✓ Passed**MOT #10** 2014-11-19 16:58**MOT test number** 935513224390**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #9** 2014-11-19 16:58**MOT test number** 465343224454**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #8** 2013-12-06 15:57**MOT test number** 438570143498**Result** ✓ Passed**Notice** Rear exhaust heat shield insecure**Notice** Offside rear belt not tested due to child seat fitted**Notice** Plastic cover below front bumper insecure**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**MOT #7**

2013-12-05 11:57

MOT test number

386849433309

Result**✗ Failed****Notice** Offside rear belt not tested due to child seat fitted**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Notice** Plastic cover below front bumper insecure**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)**Notice** Rear exhaust heat shield insecure**MOT #6**

2012-12-07 16:31

MOT test number

909162842300

Result**✓ Passed****Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5**

2011-12-06 13:26

MOT test number

798370841380

Result**✓ Passed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)



MOT #4	2010-12-07 13:59
MOT test number	524091640324
Result	✓ Passed
Notice	Osr tyre 2mm

MOT #3	2009-12-10 10:51
MOT test number	144144549358
Result	✓ Passed
Notice	Rear tyres only passed mot test today rear brake pads low rear brake binding

MOT #2	2008-11-07 10:47
MOT test number	132572618342
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Nearside wing repeater lamp loose
Notice	Rear seats (3rd row) not up at time of test , unable to check rear seat belts

MOT #1	2008-11-03 14:23
MOT test number	844798608323
Result	✗ Failed
Pass with rectification	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
Notice	Nearside wing repeater lamp loose
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Rear seats (3rd row) not up at time of test , unable to check rear seat belts
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-16
Last registration	2021-12-20
Complete history	See info



Registration #1	2005-12-16	11 mi
Registration #2	2008-11-03	20.080 mi
Registration #3	2008-11-07	20.142 mi
Registration #4	2009-12-10	29.030 mi
Registration #5	2010-12-07	36.344 mi
Registration #6	2011-12-06	42.986 mi
Registration #7	2012-12-07	49.202 mi
Registration #8	2013-12-05	1.086 mi
Registration #9	2013-12-06	1.087 mi
Registration #10	2014-11-19	4.985 mi
Registration #11	2015-12-20	20.142 mi
Registration #12	2016-12-20	20.142 mi
Registration #13	2017-12-20	20.142 mi
Registration #14	2018-12-20	20.142 mi
Registration #15	2019-12-20	20.142 mi
Registration #16	2020-12-20	20.142 mi
Registration #17	2021-12-20	20.142 mi
Registration #18	2022-12-20	20.142 mi
Registration #19	2023-12-20	20.142 mi
Registration #20	2024-12-20	20.142 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1445 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

D118628