



**SB57NSO**


report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SE
Colour	Grey
Year of manufacture	2007
Top speed	128 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	143 g/km
CO2 label	F





## MOT history

MOT expiry date	2025-02-27
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	45
Total items failed	7

MOT #20 2024-02-28 14:12

MOT test number 735143734344

Result ✓ Passed

Next expiry date 2025-02-27

- Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Play in steering rack inner joint(s)
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement N/s and o/s rear (5.3.4 (a) (i))

MOT #19 2023-02-01 17:07

MOT test number 552484726825

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18** 2023-02-01 17:07**MOT test number** 345814344646**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17** 2022-02-03 08:53**MOT test number** 956707078016**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2021-02-03 14:49**MOT test number** 645964912080**Result** ✓ Passed

**MOT #15**

2020-01-13 11:19

**MOT test number**

705777057793

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both lower arm rear bushes (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2019-01-26 12:56

**MOT test number**

852150296679

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine bay covers & under-trays fitted

**MOT #13**

2019-01-26 11:02

**MOT test number**

146798269460

**Result**

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine bay covers & under-trays fitted
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2018-05-19 12:41**MOT test number** 443399875404**Result** ✓ Passed**Advice** Condensation in o/s rear lamp but not affecting operation**Advice** Brakes could do with service/adjustment**MOT #11** 2018-05-19 10:43**MOT test number** 631904269952**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (4.1.D.1a)**Advice** Brakes could do with service/adjustment**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Condensation in o/s rear lamp but not affecting operation**MOT #10** 2017-05-22 11:54**MOT test number** 383837871565**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #9** 2017-05-17 13:31**MOT test number** 314294826979**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Nail in tyre

**MOT #8** 2016-12-08 13:57**MOT test number** 359902420105**Result** ✓ Passed**MOT #7** 2016-01-01 11:20**MOT test number** 121161247324**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-09-03 13:41**MOT test number** 308686344480**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-09-27 14:52**MOT test number** 428080173243**Result** ✓ Passed**MOT #4** 2013-09-25 08:45**MOT test number** 917278163224**Result** ✗ Failed**Notice** Rear inner brake pads appear to be on legal limit**Advice** Outer Rear Brake pad(s) wearing thin (3.5.1g)**Notice** N/s rear wheel binding**Fail** Offside rear brake binding (3.7.B.1)



MOT #3	2012-08-31 16:38
MOT test number	806674542260
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-12-05 11:09
MOT test number	416489931357
Result	✓ Passed

MOT #1	2010-12-07 09:32
MOT test number	244451340395
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-






Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-12-04
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2007-12-04	18 mi
Registration #2	2010-12-07	34.698 mi
Registration #3	2011-12-05	40.961 mi
Registration #4	2012-08-31	45.623 mi
Registration #5	2013-09-25	53.095 mi
Registration #6	2013-09-27	53.117 mi
Registration #7	2014-09-03	69.225 mi
Registration #8	2016-01-01	85.432 mi
Registration #9	2016-12-08	93.601 mi
Registration #10	2017-05-17	95.775 mi
Registration #11	2017-05-22	95.776 mi
Registration #12	2019-05-20	95.777 mi
Registration #13	2019-05-20	95.777 mi
Registration #14	2019-05-20	95.777 mi
Registration #15	2019-05-20	95.777 mi
Registration #16	2019-05-20	95.777 mi
Registration #17	2019-05-20	95.777 mi
Registration #18	2019-05-20	95.777 mi
Registration #19	2019-05-20	95.777 mi
Registration #20	2019-05-20	95.777 mi
Registration #21	2019-05-20	95.777 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1380 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	BKD C16936