



AJ09EKP

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Silver
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg






Internet history

Entry 1

Date	2021-10-03
Pictures	19
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2021-09-30 11:42
MOT test number	280250328925
Result	✓ Passed
Next expiry date	2022-10-03
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13	2020-10-02 15:35
MOT test number	133777076900
Result	✓ Passed

MOT #12	2019-03-28 15:49
MOT test number	503598548227
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11	2019-03-28 12:14
MOT test number	822150952738
Result	✗ Failed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
MAJOR	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt upper and lower (5.3.4 (b) (ii))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #10** 2018-04-04 09:02**MOT test number** 228555877292**Result** ✓ Passed**Advice** Offside Rear tyre out of shape**MOT #9** 2017-11-01 12:33**MOT test number** 864473090179**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #8** 2017-02-17 15:19**MOT test number** 109232629251**Result** ✓ Passed**Advice** Engine cover and undertray fitted**MOT #7** 2017-02-13 09:27**MOT test number** 404006499925**Result** ✗ Failed**Advice** Engine cover and undertray fitted**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** N/s/r tyre worn on inner edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #6** 2016-02-19 12:55**MOT test number** 695697208103**Result** ✓ Passed**Advice** Brake pipe to offside rear hose slightly corroded**MOT #5** 2015-11-07 12:14**MOT test number** 168370168170**Result** ✓ Passed**MOT #4** 2014-10-31 09:41**MOT test number** 657054404319**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-11-12 11:37**MOT test number** 787966713329**Result** ✓ Passed**MOT #2** 2012-11-13 11:53**MOT test number** 345718312389**Result** ✓ Passed**MOT #1** 2012-04-24 09:56**MOT test number** 937205012100**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-05-11
Last registration	2021-09-30
Complete history	See info



Registration #1	2009-05-11	25 mi
Registration #2	2012-04-24	23.991 mi
Registration #3	2012-11-13	27.368 mi
Registration #4	2013-11-12	37.361 mi
Registration #5	2014-10-31	46.179 mi
Registration #6	2015-11-07	59.215 mi
Registration #7	2016-02-19	62.447 mi
Registration #8	2017-02-13	75.626 mi
Registration #9	2018-05-20	88.805 mi
Registration #10	2019-08-27	101.984 mi
Registration #11	2020-11-24	115.163 mi
Registration #12	2021-09-30	128.342 mi
Registration #13	2022-08-27	141.521 mi
Registration #14	2023-07-24	154.700 mi
Registration #15	2024-06-21	167.879 mi
Registration #16	2025-05-18	181.058 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 173871