





General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Blue
Year of manufacture	2010
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP	0 < 101 A
Max. torque	200 Nm at 1.500 rpm	101 - 120 B
Engine capacity	1.248 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185 H
Consumption city	44.1 mpg	186 - 225 J
Consumption extra urban	62.8 mpg	225+ L
Consumption combined	54.3 mpg	





Internet history

Entry 1

Date


2021-09-22

6

Pictures

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-25
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	22
Total items failed	4

MOT #16	2024-02-26 13:49
MOT test number	193868198241
Result	✓ Passed
Next expiry date	2025-02-25

MOT #15	2022-10-10 11:03
MOT test number	319474137841
Result	✓ Passed

MOT #14	2021-10-04 14	:46
MOT test	number 1210870742	253
Result	🗙 Fai	led
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Front top mount rough when rotated	





MOT #13	2020-09-11 07:22
MOT test number	105704529384
Result	✓ Passed
MinorNearside Front Lower Windscreen damaged but not adverselwindscreen (3.2 (a) (i))AdviceNearside Front Upper slight wear to strut top bearing	y affecting driver's view stone chip to
MOT #12	2020-09-02 10:26

MOT test	number	746520966300
Result		🗙 Failed
Minor windscree	Nearside Front Lower Windscreen damaged but not adversely affecting driver's view en (3.2 (a) (i))	stone chip to
MAJOR	Offside Front Macpherson strut top bush or bearing has excessive wear or free play	(5.3.4 (a) (i))
Advice	Nearside Front Upper slight wear to strut top bearing	

MOT #11	2019-08-16 10:31
MOT test number	181405317880
Result	✓ Passed

MOT #10	2018-07-18 14:54
MOT test number	260641468623
Result	✓ Passed
Advice Items removed from driver's view prior to test	

MOT #9		2017-06-29 12:18
MOT test	number	238051827877
Result		✓ Passed
Advice (2.5.B.1b)	Offside Front Macpherson strut has slight movement in the upper support b	bearing assembly
Advice	Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	





MOT #8	2017-06-29 12:18
MOT test number	310157521070
Result	× Failed
Advice Offside Front Macpherson strut has (2.5.B.1b)	slight movement in the upper support bearing assembly
Pass with rectification Offside Rear refle	ector missing (1.5.1a)
Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	

MOT #7	2016-07-19 11	:53
MOT test	number 6205432472	241
Result	V Pass	sed
Advice	Offside Rear tyre worn on inner edge	
Advice	Nearside Rear position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)	
Advice	Offside Rear tyre tread starting to split	
Advice	Offside Rear position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)	

MOT #6	2015-06-19 09:05
MOT test number	869860875193
Result	✓ Passed

MOT #5	2015-06-16 14:54
MOT test number	787157865134
Result	🗙 Failed
FailNearside Front Direction indicator not working (1.4.A.2c)NoticeIndicator fallen out in headlamp	

MOT #4	2014-05-27 16:45
MOT test number	529557744141
Result	✓ Passed





MOT #3		2014-05-27 16:45
MOT test number		417837744157
Result		🗙 Failed
Pass with rectification	Nearside Front Direction indicator not working (1.4.A.2c)	
MOT #2		2013-06-14 16:20
MOT test number		477585063140
Result		✓ Passed
MOT #1		2013-06-14 16:20
MOT test number		299055163121
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)	



BD10ZVO report date: 2024-03-28

Tax & MOT check

X Untaxed	√ MOT	
Tax expired: 31 July 2021	Expires: 25 February 2025	
Tax status	Expired at 31 July 2021	
Days left	1002 days too late	
MOT expiry date	25 February 2025	
Full MOT history	See MOT history	





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-24
Last registration	2024-02-26
Complete history	<u>See info</u>



Registration #1	2010-07-24	7 mi
Registration #2	2013-06-14	39.816 mi
Registration #3	2014-05-27	50.498 mi
Registration #4	2015-06-16	55.729 mi
Registration #5	2015-06-19	55.729 mi
Registration #6	2016-07-19	60.946 mi
Registration #7	2017-06-29	63.920 mi
Registration #8	2017-06-29	63.920 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.117 est
Registration #15		11.777 mi
Registration #16		11.777 est





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2750 mm
Kerb weight	1345 kg
Max. allowed weight	2020 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles CarCheck.co.uk	2 page 13/13