



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	C C180 K BLUEEFFICIENCY EXECUTIVE SE
Colour	Silver
Year of manufacture	2010
Top speed	143 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	230 Nm at 4.500 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2022-08-05
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	46
Total items failed	7

MOT #142021-08-06 18:04

MOT test number704369619711

Result✓ Passed

Next expiry date2022-08-05

- AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceExhaust has a minor leak of exhaust gases (6.1.2 (a))
- AdviceRear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- AdviceRear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))
- AdviceRear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- AdviceFront Wheel bearing has slight play n/s and o/s (5.1.3 (a) (i))
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-08-06 12:17

MOT test number

354114600864

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Wheel bearing has slight play n/s and o/s (5.1.3 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt n/s and o/s (5.3.4 (b) (ii))

MOT #12

2020-07-27 14:25

MOT test number

846543506986

Result**✓ Passed**

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2019-05-01 08:33

MOT test number

579446712290

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2019-05-01 08:33

MOT test number

314247839698

Result

✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2018-05-09 08:36**MOT test number** 222648028536**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2018-05-09 08:36**MOT test number** 744462296732**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2017-03-16 11:31**MOT test number** 471592609232**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-03-16 11:31**MOT test number** 723433561475**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-03-22 16:17**MOT test number** 623334596515**Result** ✓ Passed**MOT #4** 2015-03-25 14:16**MOT test number** 818424285040**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2014-03-19 14:53**MOT test number** 766528674025**Result** ✓ Passed**MOT #2** 2013-03-11 12:08**MOT test number** 197770173073**Result** ✓ Passed



MOT #1	2013-03-11 11:04
MOT test number	709420773050
Result	✗ Failed
Fail	Offside Headlamp not working on dipped beam (1.7.5a)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-25
Last registration	2021-08-06
Complete history	See info



Registration #1	2010-03-25	27 mi
Registration #2	2013-03-11	30.437 mi
Registration #3	2013-03-11	30.437 mi
Registration #4	2014-03-19	38.263 mi
Registration #5	2015-03-25	51.894 mi
Registration #6	2016-03-22	70.980 mi
Registration #7	2017-03-16	89.454 mi
Registration #8	2017-03-16	89.454 mi
Registration #9	2019-03-20	89.454 mi
Registration #10	2019-03-20	89.454 mi
Registration #11	2019-03-20	89.454 mi
Registration #12	2019-03-20	89.454 mi
Registration #13	2019-03-20	89.454 mi
Registration #14	2019-03-20	89.454 mi
Registration #15	2021-08-06	89.454 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	70%
Pedestrian	30%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

27191031309875