





report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP	
Max. torque	186 Nm at 4.500 rpm	
Engine capacity	1.975 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	25.9 mpg	
Consumption extra urban	44.1 mpg	
Consumption combined	35.3 mpg	
CO2 emission	193 g/km	
CO2 label	J	



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2022-01-28
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-27
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	39
Total items failed	12

MOT #19		2024-01-12 14:38
MOT test	number	678399527330
Result		✓ Passed
Next expi	ry date	2025-01-27
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #18		2023-01-28 15:29
MOT test	number	850081181387
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

page 4/14

MOT #17 2021-11-23 09:13 MOT test number 196238924419

Result

✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output

(4.1.4 (b))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Headlamp has a product on the light source but not seriously reducing light output

(4.1.4 (b))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16 2021-11-22 13:05

MOT test number 847132421675

Result X Failed

Fail Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Headlamp has a product on the light source but not seriously reducing light output

(4.1.4 (b))

(4.1.4 (b))

CarCheck.co.uk

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output



report date: 2024-03-29

MOT test number

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Power steering pipe/hose slightly damaged (2.1.5 (g) (i))

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14 2020-11-17 10:26 **MOT** test number 150259612315 Result × Failed **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Fail Offside Rear Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii)) Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i)) Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii)) **Advice** Power steering pipe/hose slightly damaged (2.1.5 (g) (i)) **Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #13

MOT test number

Result

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

MOT #12

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



report date: 2024-03-29

 MOT #11
 2017-05-15 10:41

 MOT test number
 125503470520

 Result
 ✓ Passed

 MOT #10
 2017-05-15 10:41

 MOT test number
 767036782053

 Result
 X Failed

 Pass with rectification
 Nearside Stop lamp not working (1.2.1b)

MOT test number

Result

Advice (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8 2016-05-04 08:30 **MOT** test number 279115180172 Result × Failed Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Fail Nearside Stop lamp not working (1.2.1b) **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 6/14



report date: 2024-03-29

✓ Passed

2015-04-28 10:51 **MOT #7**

357978515118 **MOT** test number

Result ✓ Passed

Advice Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice (1.1.A.3b)

Result

Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50%

MOT #6 2014-05-19 08:50

MOT test number 445159634179

Result ✓ Passed

MOT #5 2014-05-14 17:15

MOT test number 246284134127

Result × Failed

Fail Nearside Steering rack gaiter split (2.2.D.2d)

Fail Offside Rear wheel bearing rough when rotated (2.6.1)

MOT #4 2013-05-03 10:39

MOT test number 457693723110

Result Passed

Notice Advise OSR tyre has a nail in it.

MOT #3 2012-05-08 11:54

MOT test number 336699022125

Result Passed

MOT #2 2011-08-11 14:53

MOT test number 937373421232

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #1 2011-08-11 12:49

MOT test number 695013721242

Result

× Failed

Pass with rectification Centre Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 8/14



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 9/14



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



Owner history

Owner History		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		DAI

	More info >	
Plate changes See in this check if this HYUNDAI had different number plates.		
See in this cheek it this months had unreferre humber plates.		
Number of plates		9
Current registration	NK NK	
Plate since		
Current registration	UK NE	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-10
Last registration	2024-01-12
Complete history	See info



Registration #1	2008-09-10	24 mi
Registration #2	2011-08-11	27.781 mi
Registration #3	2011-08-11	27.781 mi
Registration #4	2012-05-08	32.998 mi
Registration #5	2013-05-03	38.029 mi
Registration #6	2014-05-14	41.660 mi
Registration #7	2014-05-19	41.660 mi
Registration #8	2015-04-28	45.209 mi
Registration #9	2016-05-04	48.254 mi
Registration #10	2016-05-04	48.254 mi
Registration #11	2017-05-15	51.589 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

D: 1000	ensior	~ ~ C		ьь
		15 ~	W AIR	

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC7063370

CarCheck.co.uk page 14/14