




report date: 2024-03-29

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI TOUCH EDITION S/S
Colour	Red
Year of manufacture	2018
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-07
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-10
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	13
Total items failed	1

## MOT #4 2024-01-11 11:46

MOT test number 785706323780

Result ✓ Passed

Next expiry date 2025-01-10

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #3 2022-12-30 13:42

MOT test number 899452932940

Result ✓ Passed

- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing wall of tyre (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer wall of tyre (5.2.3 (d) (ii))

**MOT #2** 2022-12-29 13:13**MOT test number** 785343939300**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer wall of tyre (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing wall of tyre (5.2.3 (d) (ii))**MOT #1** 2021-11-30 08:26**MOT test number** 816111402204**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
10 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	10 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-09-30
Last registration	2024-01-11
Complete history	<a href="#">See info</a>



Registration #1	2018-09-30	13 mi
Registration #2		
Registration #3	2021-11-30	14.629 mi
Registration #4		
Registration #5		
Registration #6		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1296 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBGZ3087199