





General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	34.0 mpg
Consumption combined	28.0 mpg
CO2 emission	267 g/km
CO2 label	М







Internet history

Entry	1
Date	

Pictures

2021-07-07

33

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	25
Total items failed	19

MOT #21		2023-06-27 14:42
MOT test	number	272581250372
Result		✓ Passed
Next expi	ry date	2024-07-13
Advice	Vehicle structure is corroded but structural rigidity is not significantly redu	ced (6.1.1 (c) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1	1.11 (c))

MOT #20 2022-07-14 12:09 860887907458 **MOT test number** Result 🗸 Passed Advice Tyre slightly damaged/cracking or perishing All four (5.2.3 (d) (ii)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



HJ5	6	V	CZ
report da	te:	202	24-03-28

MOT #19	2022-07-07 11:43
MOT test number	281353375193
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Fail Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
FailRear fog lamp not working (4.5.1 (a) (ii))	
Advice Tyre slightly damaged/cracking or perishing All four (5.2.3 (d) (ii))	
Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no long ingress of dirt (6.1.7 (g) (ii))	er prevents the

MOT #18	2021-07-08 14:34
MOT test number	539230454654
Result	✓ Passed
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #17		2020-08-28 09:37
MOT test	number	608266564119
Result		✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Wheel/tyre protruding beyond wheel arch All 4	





MOT #16	2019-07-16 16:35	
MOT test number	924714647952	
Result	✓ Passed	
MOT #15	2019-07-16 16:35	
MOT test number	822590090434	
Result	× Failed	
Pass with rectification	Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
Pass with rectification	rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or	
all lamps (4.7.1 (b) (ii))		
Pass with rectification	Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	

MOT #14	2018-06-26 09:50
MOT test number	826719066942
Result	✓ Passed

MOT #13	2018-02-02 15:23
MOT test number	943238717277
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases centre box (7.1.2)	

MOT #12	2018-01-31 16:12
MOT test number	669906177670
Result	🗙 Failed
FailOffside Front Track rod end ball joint has excessive play (2.2.B.1f)AdviceExhaust has a minor leak of exhaust gases centre box (7.1.2)	





MOT #11	2017-03-25 11:29
MOT test number	945604342128
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	
MOT #10	2017-03-23 11:15
MOT test number	783952217428
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Fail Driver's door cannot be opened from inside the vehicle (6.2.B.1b)	
Advice Child Seat fitted not allowing full inspection of adult belt	
Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail Nearside Rear coil spring broken (2.4.C.1a)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #9	2016-02-20 09:28
MOT test number	108440925074
Result	✓ Passed
MOT #8	2015-03-18 14:02
MOT test number	255707375036

✓ Passed





MOT #7	2015-03-18 10:35
MOT test number	665897575064
Result	🗙 Failed
Fail Offside Rear coil spring broken (2.4.C.1a)	
Fail Electronic stability system warning lamp indicates a fault (3.4.1c)	
Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	

MOT #6	2014-08-27 12:40
MOT test number	987239934264
Result	✓ Passed

MOT #5	2013-08-28 16:34
MOT test number	365030543249
Result	✓ Passed
Advice Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2012-09-07 14:41
MOT test number	229371352275
Result	✓ Passed

MOT #3	2011-10-08 11:02
MOT test number	625431681231
Result	✓ Passed
Notice Front Brake Discs Worn	

MOT #2	2010-09-03 09:40
MOT test number	701186240252
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	





MOT #1	2009-09-04 16:27
MOT test number	281327249273
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	MOT Expires: 13 July 2024
Tax status	Valid until 1 August
Days left	95
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-06
Last registration	2023-06-27
Complete history	<u>See info</u>



Registration #2 2009-09-04 33.313 m Registration #3 2010-09-03 37.478 m Registration #4 2011-10-08 40.405 m Registration #5 2012-09-07 45.364 m Registration #6 2013-08-28 58.940 m Registration #7 2014-08-27 64.486 m Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m			
Registration #3 2010-09-03 37.478 m Registration #4 2011-10-08 40.405 m Registration #5 2012-09-07 45.364 m Registration #6 2013-08-28 58.940 m Registration #6 2013-08-28 58.940 m Registration #7 2014-08-27 64.486 m Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #10 2017-03-23 78.161 m Registration #11 2017-03-25 78.161 m Registration #12 2017-03-25 78.161 m Registration #14 Image: Station #14 Image: Station #15 Registration #15 Image: Station #16 Image: Station #16 Registration #18 Image: Station #19 Image: Station #19 Registration #20 Image: Station #20 Image: Station #20 Registration #21 Image: Station #22 Image: Station #20	Registration #1	2006-09-06	18 mi
Registration #4 2011-10-08 40.405 m Registration #5 2012-09-07 45.364 m Registration #6 2013-08-28 58.940 m Registration #7 2014-08-27 64.486 m Registration #7 2015-03-18 67.285 m Registration #8 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 Italian for the state of th	Registration #2	2009-09-04	33.313 mi
Registration #5 2012-09-07 45.364 m Registration #6 2013-08-28 58.940 m Registration #7 2014-08-27 64.486 m Registration #7 2014-08-27 64.486 m Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 Image: Stration #13 Image: Stration #14 Registration #16 Image: Stration #16 Image: Stration #16 Registration #18 Image: Stration #17 Image: Stration #18 Image: Stration #16 Registration #19 Image: Stration #19 Image: Stration #16 Image: Stration #16 Registration #20 Image: Stration #20 Image: Stration #20 Image: Stration #20 Registration #21 Image: Stration #20 Image: Stration #20 Image: Stration #20	Registration #3	2010-09-03	37.478 mi
Registration #6 2013-08-28 58.940 m Registration #7 2014-08-27 64.486 m Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 1 1 Registration #14 1 1 Registration #16 1 1 Registration #17 1 1 Registration #18 1 1 Registration #19 1 1 Registration #20 1 1 Registration #21 1 1	Registration #4	2011-10-08	40.405 mi
Registration #7 2014-08-27 64.486 m Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-23 78.161 m Registration #13 78.161 m 78.161 m Registration #14 78.161 m 78.161 m Registration #15 78.161 m 78.161 m Registration #14 78.161 m 78.161 m Registration #14 78.161 m 78.161 m Registration #14 78.161 m 78.161 m Registration #15 78.161 m 78.161 m Registration #16 79.700 m 79.700 m Registration #17 79.700 m 79.700 m Registration #18 79.700 m 70.700 m Registration #20 70.700 m 70.700 m Registration #21 70.700 m 70.700 m Registration #22 70.700 m 70.700 m	Registration #5	2012-09-07	45.364 mi
Registration #8 2015-03-18 67.285 m Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 2017-03-25 78.161 m Registration #14 2017-03-25 78.161 m Registration #15 2017-03-25 78.161 m Registration #16 2017-03-25 78.161 m Registration #17 2017-03-25 78.161 m Registration #17 2017-03-25 78.161 m Registration #18 2017-03-25 78.161 m Registration #19 2017-03-25 78.161 m Registration #21 2017-03-25 78.161 m Registration #22 2017-03-25 78.161 m	Registration #6	2013-08-28	58.940 mi
Registration #9 2015-03-18 67.285 m Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 2017-03-25 78.161 m Registration #14 2017-03-25 78.161 m Registration #15 2017-03-25 78.161 m Registration #16 2017-03-25 2017-03-25 Registration #17 2017-03-25 2017-03-25 Registration #18 2017-03-25 2017-03-25 Registration #20 2017-03-25 2017-03-25 Registration #21 2017-03-25 2017-03-25 Registration #22 2017-03-25 2017-03-25	Registration #7	2014-08-27	64.486 mi
Registration #10 2016-02-20 71.903 m Registration #11 2017-03-23 78.161 m Registration #12 2017-03-25 78.161 m Registration #13 2017-03-25 78.161 m Registration #14 2017-03-25 78.161 m Registration #15 2017-03-25 78.161 m Registration #16 2017-03-25 2017-03-25 Registration #17 2017-03-25 2017-03-25 Registration #18 2017-03-25 2017-03-25 Registration #20 2017-03-25 2017-03-25 Registration #21 2017-03-25 2017-03-25 Registration #22 2017-03-25 2017-03-25	Registration #8	2015-03-18	67.285 mi
Registration #112017-03-2378.161 mRegistration #122017-03-2578.161 mRegistration #132017-03-2578.161 mRegistration #14Control Control Con	Registration #9	2015-03-18	67.285 mi
Registration #122017-03-2578.161 mRegistration #13Registration #1478.161 mRegistration #1478.161 m78.161 mRegistration #1578.161 m78.161 mRegistration #1678.161 m78.161 mRegistration #1678.161 m78.161 mRegistration #1778.161 m78.161 mRegistration #1878.161 m78.161 mRegistration #1978.161 m78.161 mRegistration #2078.161 m78.161 mRegistration #2178.161 m78.161 mRegistration #2278.161 m78.161 m	Registration #10	2016-02-20	71.903 mi
Registration #13Registration #14Registration #15Registration #16Registration #17Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22	Registration #11	2017-03-23	78.161 mi
Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22	Registration #12	2017-03-25	78.161 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #13		11.777 esi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #14		11.112 esi
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #15		11.112 esi
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #16		11.112 esi
Registration #19 Registration #20 Registration #21 Registration #22	Registration #17		11.112 esi
Registration #20 Registration #21 Registration #22	Registration #18		11.112 esi
Registration #21 Registration #22	Registration #19		11.777 esi
Registration #22	Registration #20		11.317 est
	Registration #21		11.117 esi
Registration #23	Registration #22		11.117 esi
	Registration #23		11.777 est

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2195 kg
Max. allowed weight	2880 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/15

page 15/15

Number of axles	2
Engine number	750331