





report date: 2024-03-28

General information

Make	FIAT
Model	FIORINO 16V MULTIJET COMBI ADVENTURE
Colour	White
Year of manufacture	2013
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-29

Pictures 11

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-06
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #10	2023-10-06 14:59
MOT test number	373821720803
Result	✓ Passed
Next expiry date	2024-10-06
Advice Power steering component has slight seepage from a component (2.1.5 (a))	

MOT #9	2022-10-06 15:09
MOT test number	456921029956
Result	✓ Passed
Advice Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Diesel injector seal leaking	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Power steering component has slight seepage from a component (2.1.5 (a))	

MOT #8	2021-10-07 10:25
MOT test number	409355198635
Result	✓ Passed
Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) Advice Bonnet latch worn) (i))

CarCheck.co.uk page 3/12



2021-10-01 11:07 **MOT #7** 367899067984 **MOT** test number Result × Failed Fail Offside Front Macpherson strut pin or bush excessively worn (5.3.4 (a) (i)) Bonnet latch worn **Advice** Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) **Fail**

MOT #6

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Bonnet stay damaged

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5		2019-10-03 09:26
MOT test	number	385372807988
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge out of shape (5.2.3 (e))
Advice	4 ODD TYRES	
Advice	Bonnet primary retaining device slightly deteriorated stay for upright position da	amaged (3.1 (c))
Advice (d))	Parking brake lever defective but can be satisfactorily operated insufficient rese	rve travel (1.1.6

CarCheck.co.uk page 4/12



MOT #4 2018-09-29 13:42 **MOT test number** 946186586654 Result Passed **Advice** Nearside Rear Nail in tyre Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT #3 2017-10-02 13:49 **MOT** test number 614593281861 Result ✓ Passed MOT #2 2016-10-04 08:37 **MOT test number** 441837950267 ✓ Passed Result **MOT #1** 2016-10-04 08:37

MOT test number 393232861652

Result × Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK 312
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-30
Last registration	2023-10-06
Complete history	See info



Registration #1	2013-09-30	11 mi
Registration #2	2016-10-04	40.396 mi
Registration #3	2016-10-04	40.396 mi
Registration #4	2017-10-02	54.529 mi
Registration #5	2018-09-29	108.544 mi
Registration #6	2019-10-03	142.567 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777-eq

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4
Engine number	5009170

CarCheck.co.uk page 12/12