

Ford



General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	187 g/km
CO2 label	J









Internet history

Entry 1	
Date	2021-06-12
Pictures	12
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	16
Total items failed	10

MOT #14 2	023-11-27 10:48
MOT test number	354633310141
Result	🗸 Passed
Next expiry date	2024-12-21
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #13	2022-12-22 08:47
MOT test number	195551080655
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2021-12-21 17:25
MOT test	number	967253407494
Result		✓ Passed
Advice	Oil leak, but not excessive Back of engine/ turbo area (8.4.1 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner + outer edge (5.2.3 (e))		.3 (e))
Advice	Nearside Rear Nail in tyre	





MOT #11	2021-12-21 12:12
MOT test number	930051681766
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner + outer edge (5	5.2.3 (e))
Advice Nearside Rear Nail in tyre	
Fail Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
Advice Oil leak, but not excessive Back of engine/ turbo area (8.4.1 (a) (i))	
Fail Tyre has ply or cords exposed NSF + OSF (5.2.3 (d) (ii))	
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
FailOffside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingres(ii))	ss of dirt (5.3.4 (b)

MOT #10	2020-12-09 10:51
MOT test number	364753374929
Result	✓ Passed

МОТ #9	2020-12-07 15:54
MOT test number	128879801749
Result	🗙 Failed
Fail Offside Front Tyre has ply or cords exposed 235-40-18 continental (5.2.3 (d) (ii))	
Fail Nearside Rear Registration plate lamp does not illuminate simultaneously with th (4.7.2 (a))	e position lamps
Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a)	(i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	





MOT #8		2019-06-20 08:41
MOT test	number	373871478910
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Child Seat fitted not allowing full inspection of adult belt X2	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2018-06-04 09:16
MOT test number	444387768144
Result	✓ Passed
МОТ #6	2017-06-13 09:08
MOT test number	886571004441
Result	✓ Passed
MOT #5	2016-06-23 09:05
MOT test number	906838546931
Result	✓ Passed
MOT #4	2015-06-11 13:33
MOT test number	545372765192
Result	✓ Passed





MOT #3		2014-06-17 14:31
MOT test	number	259858264155
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #2	2013-06-21 15:58
MOT test number	735932973127
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #1	2013-02-11 14:42

	2013-02-11 14.42
MOT test number	177932543481
Result	✓ Passed



FE10RUV report date: 2024-03-28

Tax & MOT check

Taxed Tax due: 1 August 2024	✓ MOT Expires: 21 December 2024
Tax status	Valid until 1 August
Days left	95
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-23
Last registration	2023-11-27
Complete history	<u>See info</u>



Registration #1	2010-03-23	18 mi
Registration #2	2013-02-11	39.361 mi
Registration #3	2013-06-21	42.081 mi
Registration #4	2014-06-17	50.795 mi
Registration #5	2015-06-11	60.133 mi
Registration #6	2016-06-23	67.361 mi
Registration #7	2017-06-13	72.553 mi
Registration #8	2018-06-04	77.668 mi
Registration #9		10.777 est
Registration #9 Registration #10		11.777 est
-		01,000 est 01,000 est 01,000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11 Registration #12		00,000 460 01,000 460 01,000 460 01,000 460 01,000 460 01,000 460
Registration #10 Registration #11 Registration #12 Registration #13		01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1592 kg
Max. allowed weight	2190 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AL32300