





report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Black
Year of manufacture	2004
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	117 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/17



Internet history

Entry 1

Date 2021-10-01

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT expiry date	2025-03-27
MOT pass rate	55 %
MOT passed	18
Failed MOT tests	15
Total advice items	34
Total items failed	33

MOT #33		2024-03-05 16:48
MOT test	number	268760754342
Result		✓ Passed
Next expi	iry date	2025-03-27
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously reducing	g light output (4.1.4
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing l	ight output (4.1.4

MOT #32	2024-03-05 14:13
MOT #32	2024-03-05 14:1

MOT test number 500842390447

Result × Failed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Power steering pipe/hose leaking into steering rack. few pipes connected invastigate right one (2.1.5 (a))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 3/17



MOT #31 2023-03-24 17:24

MOT test number 218489034087

Result
✓ Passed

Advice Front Upper Oil leak, but not excessive (8.4.1 (a) (i))

Advice Coolant leak

MOT #30 2023-03-24 14:07

MOT test number 946414718042

Result X Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Upper Oil leak, but not excessive (8.4.1 (a) (i))

Advice Coolant leak

MOT #29 2022-03-28 09:19

MOT test number 467666357129

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/17



MOT #28 2022-03-11 11:24

MOT test number 987852872738

Result X Failed

Fail Nearside Front Outer Tyre has a tear, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))

Fail Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #27 2021-03-11 10:47

MOT test number 128767350649

Result ✓ Passed

MOT #26 2021-03-04 10:45

MOT test number 843260453922

Result X Failed

Fail Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #25 2020-02-21 16:03

MOT test number 789658633733

Result ✓ Passed

CarCheck.co.uk page 5/17



Result

LK04EYT report date: 2024-03-28

× Failed

MOT #24 2020-02-13 14:34

MOT test number 889100406622

Result X Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #23 2019-02-19 16:45

MOT test number 399383983261

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22 2019-02-19 16:45

MOT test number 285981178425

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21 2018-02-15 15:57

MOT test number 201486154812

MOT #20 2018-02-15 15:57

MOT test number 263136426807

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 6/17



MOT #19 2017-02-25 11:02 MOT test number 735840773943

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #18 2017-02-25 11:02

MOT test number 309866119090

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #17 2016-02-13 10:30

MOT test number 699978741035

Result \(\sqrt{Passed} \)

MOT #16 2016-02-13 10:30

MOT test number 340928884532

Result X Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

MOT #15 2015-02-28 10:54

MOT test number 995439455096

Result
✓ Passed

MOT #14 2014-03-12 14:50

MOT test number 875681974078

Result
✓ Passed

CarCheck.co.uk page 7/17



MOT #13 2014-03-01 11:05

MOT test number 169290964408

Result X Failed

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #12 2013-02-26 09:32

MOT test number 179757353078

Result \rightarrow Passed

Notice AIR BAG LIGHT ON

MOT #11 2013-02-26 09:32

MOT test number 196937353422

Result X Failed

Notice AIR BAG LIGHT ON

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #10 2012-02-23 08:57

MOT test number 367984452028

MOT #9 2012-02-23 08:57

MOT test number 887404252084

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 8/17



MOT #8 2011-02-25 16:13

245516951088 **MOT** test number

Result ✓ Passed

MOT #7 2011-02-25 09:53

MOT test number 309206351010

Result × Failed

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Exhaust has a major leak of exhaust gases (7.1.2)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

MOT #6 2010-02-02 16:22

MOT test number 163993730436

Result ✓ Passed

MOT #5 2010-02-02 09:42

580103930030

Result × Failed

Fail Rear registration plate deteriorated (6.3.1d)

MOT test number

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2009-02-24 16:49

MOT test number 323985459017

Result ✓ Passed

Notice Water damage to rear number plate .only just passed test

Notice Both front wiper blades worn

CarCheck.co.uk page 9/17



× Failed

MOT #3 2008-02-08 09:54

MOT test number 633699438010

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Rear number plate deteriorated

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Rear wiper blade split

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2008-02-08 09:54

MOT test number 480639538004

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Notice Rear number plate deteriorated

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear wiper blade split

Pass with rectification Nearside Front Headlamp aim aimed so that it dazzles other road users

(1.8.A.1a)

Result

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2007-02-22 09:45

MOT test number 143093657022

Result ✓ Passed

CarCheck.co.uk page 10/17



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 11/17



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner	biotom,
UWNEL	nisiniv

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		NDAI
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK C	
Plate since		
	More info	>

CarCheck.co.uk page 14/17



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	2004-03-01
Last registration	2024-03-05
Complete history	See info



Registration #1	2004-03-01	18 mi
Registration #2	2007-02-22	28.779 mi
Registration #3	2008-02-08	38.059 mi
Registration #4	2009-02-24	45.579 mi
Registration #5	2010-02-02	50.603 mi
Registration #6	2010-02-02	50.603 mi
Registration #7	2011-02-25	54.818 mi
Registration #8	2011-02-25	54.820 mi
Registration #9	2012-02-23	57.603 mi
Registration #10	2013-02-26	60.023 mi
Registration #11	2014-03-01	63.099 mi
Registration #12	2014-03-12	63.136 mi
Registration #13	2015-02-28	66.934 mi
Registration #14	2016-02-13	70.300 mi
Registration #15	2016-02-13	70.300 mi
Registration #16	2017-02-25	73.470 mi
Registration #17		0.074
Registration #18		11.777 es
Registration #19		11,177 es
Registration #20		11.777 es
Registration #21		0.07466
Registration #22		11,777 es
Registration #23		11,177 es
Registration #24		11,777 es
Registration #25		11,777 ms
Registration #26		71,777 es
CarCheck.co.uk		page 16/17

Registration #27	11.777 66
Registration #28	11.777 es
Registration #29	11.777 es
Registration #30	11.777 es
Registration #31	9.79 es
Registration #32	0.777-46

More info >



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1072 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of axles CarCheck.co.uk	2 page 17/17	