





### General information

Make	RENAULT
Model	MEGANE PRIVILEGE T 165 EU4
Colour	Grey
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	165 BHP
Max. torque	270 Nm at 3.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	196 g/km
CO2 label	J





# MOT history

MOT expiry date	2021-03-04
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	25
Total items failed	12

MOT #18	2020-02-29 11:05
MOT test number	798719769199
Result	✓ Passed
Next expiry date	2021-03-04
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2020-02-29 08:36
MOT test number	597181606621
Result	🗙 Failed
Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of di	rt insecure (2.1.3 (g) (ii))
Fail         Offside Steering rack gaiter missing or no longer prevents the ingress of dirt	insecure (2.1.3 (g) (ii))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16		2019-03-01 14:49
MOT test i	number	757235794692
Result		✓ Passed
Advice	Engine mounting damaged but not to excess both rears (6.1.8 (a) (i))	
Advice	Engine emitted white smoke at the end of emissions test	
Advice	Offside steering rack boot loose	





MOT #15	2018-02-23 16:53
MOT test number	347479225845
Result	✓ Passed
MOT #14	2018-02-23 16:53
MOT test number	500481511771
Result	🗙 Failed

**Pass with rectification** Battery insecure (1.9.1)

MOT #13		2017-03-05 12:00
MOT test	number	661903545061
Result		✓ Passed
Advice	Non obligatory mirror damaged	
Advice	Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
Advice	Play in steering rack inner joint(s)	

MOT #12	2017-03-05 10:55
MOT test number	915901769652
Result	🗙 Failed
Advice Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
Advice Play in steering rack inner joint(s)	
Fail   Emissions not tested (7.3.A.1)	
Advice Non obligatory mirror damaged	



MOT #11	2016-06-29 08:47
MOT test number	666651028138
Result	🗙 Failed
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
FailSteering lock fails to engage (2.1.4b)	
Advice Nearside Inner Ball joint has slight play steering arm (2.2.B.1f)	
Advice Nearside Non obligatory mirror damaged	
<b>Fail</b> Offside Front position lamp(s) not working (1.1.A.3b)	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
<b>Fail</b> Offside Inner Ball joint has excessive play steering arm (2.2.B.1f)	
Advice Coolant leak	
Advice Play in steering rack inner joint(s)	
Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1	2a)

MOT #10	2015-06-04 17:00
MOT test number	176425355185
Result	✓ Passed

MOT #9	2014-06-11 16:30
MOT test number	765622064101
Result	✓ Passed
Advice Offside Steering pivot point has slight play (2.2.B.1g)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

**RF06TZU** 

report date: 2024-03-28





MOT #8	2014-06-11 14:28
MOT test number	106942364155
Result	🗙 Failed
Fail       Offside Outer Front constant velocity joint gaiter insecure to the extent that ingress of dirt etc (2.5.C.1a)         Advice       Nearside Front Tyre worn close to the legal limit (4.1.E.1)	it no longer prevents the
AdviceNearside Front Tyre worn close to the legal limit (4.1.E.1)AdviceOffside Steering pivot point has slight play (2.2.B.1g)	

MOT #7	2013-07-11 13:38
MOT test number	628042593115
Result	✓ Passed
Advice Offside Front Steering pivot point has slight play (2.2.B.1g)	

MOT #6	2012-05-03 15:49
MOT test number	655784122156
Result	Passed
Advice Offside Steering pivot point has slight play (2.2.B.1g)	

MOT #5	2012-05-03 15:49
MOT test number	909924322172
Result	× Failed
<b>Pass with rectification</b> structure (4.1.D.1b)	Offside Rear Tyre has a lump, caused by separation or partial failure of its
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice Offside Steering pivot point has slight play (2.2.B.1g)	

MOT #4	2011-04-21 11:17
MOT test number	686581811125
Result	✓ Passed





MOT #3	2010-04-28 17:17
MOT test number	812428110171
Result	✓ Passed
MOT #2	2009-06-16 11:54
MOT test number	433597269178
Result	✓ Passed
MOT #1	2009-03-20 09:45
MOT test number	962149579051
Result	✓ Passed
Advice Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice Nearside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	



Tax & MOT check

X Untaxed Tax expired: 12 December 2020	<b>X</b> <b>MOT</b> Expired: 4 March 2021
Tax status	Expired at 12 December 2020
Days left	1234 days too late
MOT expiry date	4 March 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



RF06TZU report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-06-12
Last registration	2020-02-29
Complete history	<u>See info</u>



Registration #1	2006-06-12	23 mi
Registration #2	2009-03-20	22.148 mi
Registration #3	2009-06-16	23.051 mi
Registration #4	2010-04-28	26.045 mi
Registration #5	2011-04-21	31.780 mi
Registration #6	2012-05-03	40.250 mi
Registration #7	2013-07-11	47.948 mi
Registration #8	2014-06-11	54.755 mi
Registration #9	2014-06-11	54.755 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Max. allowed weight	1845 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection

**Engine number** 

C089855