





report date: 2024-03-28

#### General information

Make	FIAT
Model	TIPO MULTIAIR POP STAR
Colour	Blue
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	140 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-07
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #6	2023-06-30 14:51
MOT test number	660495036368
Result	✓ Passed
Next expiry date	2024-07-07

MOT #5	2022-06-29 15:26
MOT test number	215719543502
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-07-08 10:14
MOT test number	794229377701
Result	<b>✓</b> Passed

Kesuit		✓ Passed
MOT #3		2021-07-06 12:07
MOT test	number	367824048284
Result		🗙 Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	))
Fail Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))

CarCheck.co.uk page 3/12



CV66YXD

report date: 2024-03-28

**MOT #2** 2019-11-06 12:59

MOT test number 357821906520

Result 
✓ Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Unable to check underside and outer sills fully due to covers

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



CV66YXD

report date: 2024-03-28

**MOT #1** 2019-10-24 10:43

**MOT test number** 503997929311

Result × Failed Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) **Advice** Unable to check underside and outer sills fully due to covers Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



CV66YXD

report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report		
********		
***************************************		
	More info >	
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	NE SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-21
Last registration	2023-06-30
Complete history	See info



Registration #1	2016-10-21	20 mi
Registration #2	2019-10-24	23.636 mi
Registration #3	2019-11-06	23.636 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	***
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1796 mm
Height	1600 mm
Length	4248 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

# Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2
Engine number 2052615