



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-21
Pictures	15
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-07-07
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	34
Total items failed	7

MOT #12 2023-07-04 11:47

MOT test number 109227683080

Result ✓ Passed

Next expiry date 2024-07-07

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2022-07-05 10:18

MOT test number 421665407342

Result ✓ Passed

**Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Tyre slightly damaged/cracking or perishing 2x rear (5.2.3 (d) (ii))

**Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #10 2021-07-08 13:15

MOT test number 646829686188

Result ✓ Passed

**MOT #9**

2021-07-06 10:23

**MOT test number**

662489666061

**Result**

✗ Failed

**Fail** Nearside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Fuel Pipe/s corroded**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #8**

2018-07-20 08:44

**MOT test number**

363103794954

**Result**

✓ Passed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #7**

2017-07-24 11:21

**MOT test number**

548550355822

**Result**

✓ Passed

**Advice** Brake pipe slightly corroded both front (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake pipe slightly corroded both rear (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2016-07-25 11:07

**MOT test number**

819085178939

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #5**

2016-07-23 11:53

**MOT test number**

895016722752

**Result**

✗ Failed

- Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Fail** Horn not working (1.6.2a)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)

**MOT #4**

2015-07-27 10:14

**MOT test number**

346498905204

**Result**

✓ Passed

**MOT #3** 2014-07-25 12:59**MOT test number** 966416804237**Result** ✓ Passed**Notice** Offside rear tyre heavily perished in tread grooves**Notice** Offside front lower suspension arm rear bush starting to separate from its bonding**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-08-02 09:13**MOT test number** 136344213203**Result** ✓ Passed**Notice** Nearside front tyre wearing on outer edge 155 55 14**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2012-07-31 09:39**MOT test number** 388483712426**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
7 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	7 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-11-21
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2009-11-21	9 mi
Registration #2	2012-07-31	10.582 mi
Registration #3	2013-08-02	18.553 mi
Registration #4	2014-07-25	23.947 mi
Registration #5	2015-07-27	30.818 mi
Registration #6	2016-07-23	37.106 mi
Registration #7	2016-07-25	37.106 mi
Registration #8	2016-07-25	37.106 mi
Registration #9	2016-07-25	37.106 mi
Registration #10	2016-07-25	37.106 mi
Registration #11	2016-07-25	37.106 mi
Registration #12	2016-07-25	37.106 mi
Registration #13	2016-07-25	37.106 mi
Registration #14	2016-07-25	37.106 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462