



report date: 2024-03-29

General information

Make	HONDA
Model	S2000 16V GT
Colour	Black
Year of manufacture	2007
Top speed	150 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	240 BHP
Max. torque	208 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.3 mpg
CO2 emission	236 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-25
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	37
Total items failed	17

MOT #23	2024-01-18 10:05
MOT test number	390743814083
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear ,ok for now (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear ,ok for now (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output may need a polish before next test (4.1.4 (b))

MOT #22	2024-01-18 10:05
MOT test number	279273926661
Result	✗ Failed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear ,ok for now (5.3.4 (a) (i))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear ,ok for now (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output may need a polish before next test (4.1.4 (b))

**MOT #21**

2023-01-19 11:18

MOT test number

430783827103

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Offside Front brake backing /dust cover broken off ,removed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20

2022-01-21 11:42

MOT test number

254646004616

Result

✓ Passed

MOT #19

2022-01-19 13:53

MOT test number

554205574081

Result

✗ Failed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources 1 of 2 (4.7.1 (b) (i))

Fail Offside Headlamp aim too high (4.1.2 (a))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2021-06-16 13:08

MOT test number

284912328669

Result

✓ Passed

MOT #17

2020-06-03 08:36

MOT test number

882627211957

Result

✓ Passed

**MOT #16**

2019-10-29 16:20

MOT test number

877019877088

Result

✓ Passed

Advice Suspension arms front + back corroded**Advice** Front Tyre slightly damaged/cracking or perishing both fronts perishing + wearing on outer edge (5.2.3 (d) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both rears perishing (5.2.3 (d) (ii))**MOT #15**

2019-10-29 09:28

MOT test number

736214053861

Result

✗ Failed

Advice Front Tyre slightly damaged/cracking or perishing both fronts perishing + wearing on outer edge (5.2.3 (d) (ii))**Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing both rears perishing (5.2.3 (d) (ii))**Advice** Suspension arms front + back corroded**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Exhaust has a minor leak of exhaust gases cat + twin back box join (6.1.2 (a))**MOT #14**

2018-10-27 10:26

MOT test number

774151331688

Result

✓ Passed

Advice Offside Front Brake has a slight bind**MOT #13**

2018-10-27 10:26

MOT test number

937861073293

Result

✗ Failed

Pass with rectification Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Brake has a slight bind

**MOT #12** 2017-10-26 14:50**MOT test number** 641074860299**Result** ✓ Passed**MOT #11** 2017-10-26 07:59**MOT test number** 753044963632**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim too high (1.8)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Headlamp aim too high (1.8)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10 2016-11-05 10:48**MOT test number** 478653703003**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #9 2015-10-19 16:14**MOT test number** 706822626599**Result** ✓ Passed**MOT #8** 2015-10-17 08:49**MOT test number** 427517734617**Result** ✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Bonnet cannot be secured in the closed position (8.4.1)
- Fail** Offside Front Anti-roll bar linkage fractured (2.4.G.1)

**MOT #7** 2014-11-07 16:37**MOT test number** 466081114454**Result** ✓ Passed**MOT #6** 2014-11-07 12:42**MOT test number** 395631814383**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Nearside Front Brake pipe inadequately supported (3.6.B.1)**Fail** Offside Rear fog lamp emits a light other than red (1.3.2e)**MOT #5** 2013-11-09 12:25**MOT test number** 878913513348**Result** ✓ Passed**Notice** Slight damage to both n/s wheel rims & n/s rear tyre**Notice** Both rear tyres are wearing on the inside shoulders**MOT #4** 2013-11-09 10:12**MOT test number** 436353413404**Result** ✗ Failed**Notice** Both rear tyres are wearing on the inside shoulders**Notice** Slight damage to both n/s wheel rims & n/s rear tyre**Fail** Offside Rear fog lamp emits a light other than red (1.3.2e)**MOT #3** 2012-11-10 10:10**MOT test number** 256325912348**Result** ✓ Passed



MOT #2	2011-11-09 16:21
MOT test number	406423411443
Result	✓ Passed

MOT #1	2010-10-04 13:57
MOT test number	852297070293
Result	✓ Passed

- Notice** Advise headlight pattern on lower limit
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Advise handbrake reserve travel
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Advise offside rear tyre has cut in tread



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	SD57UZL
Plate since	2019-03-29
Current registration	SD57UZL
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-09-28
Last registration	2024-01-18
Complete history	See info



Registration #1	2007-09-28	7 mi
Registration #2	2010-10-04	15.458 mi
Registration #3	2011-11-09	20.126 mi
Registration #4	2012-11-10	31.896 mi
Registration #5	2013-11-09	40.550 mi
Registration #6	2013-11-09	40.575 mi
Registration #7	2014-11-07	48.281 mi
Registration #8	2014-11-07	48.281 mi
Registration #9	2015-10-17	55.248 mi
Registration #10	2015-10-19	55.248 mi
Registration #11	2016-11-05	63.205 mi
Registration #12	2017-10-26	71.251 mi
Registration #13	2017-10-26	71.251 mi
Registration #14	2018-10-26	71.251 mi
Registration #15	2018-10-26	71.251 mi
Registration #16	2018-10-26	71.251 mi
Registration #17	2018-10-26	71.251 mi
Registration #18	2018-10-26	71.251 mi
Registration #19	2018-10-26	71.251 mi
Registration #20	2018-10-26	71.251 mi
Registration #21	2018-10-26	71.251 mi
Registration #22	2018-10-26	71.251 mi
Registration #23	2018-10-26	71.251 mi
Registration #24	2018-10-26	71.251 mi
Registration #25	2018-10-26	71.251 mi



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1295 mm
Length	4140 mm
Kerb weight	1260 kg
Max. allowed weight	1386 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	F20C21070174