





## General information

Make	ΤΟΥΟΤΑ
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Grey
Year of manufacture	2011
Top speed	106 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	169 BHP	0 < 101 A
Max. torque	343 Nm at 3.400 rpm	101 - 120 B
Engine capacity	2.982 cc	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185 H
Consumption city	29.7 mpg	186 - 225 J
Consumption extra urban	42.2 mpg	225+ L
Consumption combined	36.7 mpg	





# Internet history

Entry 1	
Date	2021-10-16
Pictures	28

Listing price

View report



source: cargurus.co.uk





# MOT history

MOT expiry date	2024-10-02
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	14
Total items failed	7

MOT #15	2023-09-19 10:03
MOT test number	429158735398
Result	✓ Passed
Next expiry date	2024-10-02
Advice Nearside Rear Nail in tyre	

2023-09-19 08:36
er 233328782194
× Failed
side Rear Nail in tyre lamp not working (4.5.1 (a) (ii))
lamp not working (4.5.1 (a) (ii))

MOT #13	2022-09-06 10:58
MOT test number	917412354505
Result	✓ Passed





MOT #3	12	2022-09-05 09:12
MOT te	st number	693586747180
Result		🗙 Failed
Fail	Front Fuel pipe so insecure there is a risk of fire Fuel filter insecure (6.1.3 (a) (ii))	
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)	)
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6	(c))

MOT #11	2021-09-20 07:47
MOT test number	636842777969
Result	✓ Passed
Advice Slight travel on handbrake	

MOT #10		2021-09-20 07:47
MOT test number		947313816930
Result		🗙 Failed
Advice Slight travel on handbrake		
Pass with rectification	Front Headlamp aim too high both (4.1.2 (a))	

MOT #9		2020-10-03 13:31
MOT test	number	341348062290
Result		✓ Passed
Minor	Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))
Advice	Nearside Rear Nail in tyre	
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated Both (5.3.4	(b) (i))
Advice	Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	





МОТ #8	2019-09-17 07:31
MOT test number	892040761106
Result	Passed
MinorFront Anti-roll bar linkage ball joint dust cover severely deteriorated Both (5.3.AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))	4 (b) (i))

MOT #7	2018-06-25 08:39
MOT test number	890056232333
Result	✓ Passed
МОТ #6	2017-06-26 10:16
MOT test number	329241670958
Result	✓ Passed
MOT #5	2016-06-23 08:52
MOT test number	317845938655
Result	✓ Passed
MOT #4	2016-06-23 08:52
MOT test number	220615856111

Pass with rectification Front Brak

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

МОТ #3	2015-06-26 07:56
MOT test number	358287775130
Result	✓ Passed

Result

**X** Failed





MOT #2	2014-06-11 12:13
MOT test number	469022464100
Result	✓ Passed
AdviceWindscreen has damage to an area less than a 40mm circle outsiAdviceTyre worn close to the legal limit (4.1.E.1)	de zone 'A' (8.3.1d)
MOT #1 MOT test number	2014-06-11 12:13 536352164133

			50552101155
Result			🗙 Failed
Pass with	rectification	Offside Headlamp aim too high (1.8)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)			
Advice T	yre worn close	to the legal limit (4.1.E.1)	



Tax & MOT check







### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	e et a
Date	 *
Category	 amer
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-27
Last registration	2023-09-19
Complete history	<u>See info</u>



Registration #1	2011-06-27	9 mi
Registration #2	2014-06-11	29.076 mi
Registration #3	2015-06-26	38.977 mi
Registration #4	2016-06-23	48.907 mi
Registration #5	2016-06-23	48.907 mi
Registration #6	2017-06-26	56.124 mi
Registration #7	2018-06-25	62.688 mi
Registration #8	2019-09-17	73.022 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.117 esi
Registration #15		11.777 mi





### Car features

S0225	Air conditionin
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

## Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	1975 kg
Max. allowed weight	3080 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD5220094