





report date: 2024-03-29

General information

Make	DMM
Make	BMW
Model	116 116D M SPORT
Colour	Silver
Year of manufacture	2016
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



YK660VZ

report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-12

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-24
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #7	2023-06-13 10:57
MOT test number	988520457880
Result	✓ Passed
Next expiry date	2024-06-24

MOT #6	5	2023-06-09 12:57
MOT te	st number	486753915123
Result		X Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its struc	cture (5.2.3 (d) (ii))
Advic	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #5	2022-06-16 09:15
MOT test number	891753820706
Result	✓ Passed
Advice Offside Front Road wheel slightly distorted on inner rim (5.2.2 (c) (i))	

MOT #4	2021-06-25 09:30
MOT test number	840171162008
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2020-12-21 15:33

MOT test number 549684469694

Result ✓ Passed

Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-11-15 09:27

MOT test number 157192810370

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-10-29 14:43

MOT test number 189335398555

Result X Failed

Advice Nearside Front Inner Nail in tyre

Fail

Nearside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



YK660VZ

report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners described the current and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



YK660VZ

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-18
Last registration	2023-06-13
Complete history	See info



Registration #1	2016-11-18	15 mi
Registration #2	2019-10-29	60.941 mi
Registration #3	2019-11-15	62.295 mi
Registration #4	2020-12-21	72.898 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	52 l	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ige 11/11

Number of axles 2

Engine number 38409596