



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	White
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-24
Pictures	26
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #8	2023-01-26 11:51
MOT test number	104980028394
Result	✓ Passed
Next expiry date	2024-02-20
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))

MOT #7	2022-02-21 14:34
MOT test number	858780354695
Result	✓ Passed

MOT #6	2022-02-20 22:56
MOT test number	811873890997
Result	✗ Failed
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #5	2021-04-23 10:44
MOT test number	188592205365
Result	✓ Passed
Advice	Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #4** 2020-05-09 07:42**MOT test number** 267382207399**Result** ✓ Passed**MOT #3** 2019-05-13 11:59**MOT test number** 639058250941**Result** ✓ Passed**MOT #2** 2018-11-17 09:36**MOT test number** 634655229712**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-10-27 09:37**MOT test number** 461535165301**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-11-27
Last registration	2023-01-26
Complete history	See info



Registration #1	2014-11-27	12 mi
Registration #2	2017-10-27	24.608 mi
Registration #3	2018-11-17	34.404 mi
Registration #4	2019-05-13	38.781 mi
Registration #5	2020-05-09	42.544 mi
Registration #6	2021-05-09	45.317 mi
Registration #7	2022-05-09	48.090 mi
Registration #8	2023-01-26	50.863 mi
Registration #9	2023-01-26	50.863 mi
Registration #10	2023-01-26	50.863 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FDEZ867300