



SAI2KLF

report date: 2024-03-28

General information

Make	MINI
Model	MINI ONE
Colour	Red
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	22
Total items failed	9

MOT #17 2024-01-24 16:42

MOT test number 710954531430

Result ✓ Passed

Next expiry date 2025-01-24

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16 2024-01-24 14:16

MOT test number 535882788310

Result ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Emissions unable to be completed (8.2.1.2 (d))
- Fail** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))

MOT #15 2023-01-17 16:25

MOT test number 834472230324

Result ✓ Passed

**MOT #14** 2023-01-10 12:45**MOT test number** 412815182172**Result** ✗ Failed**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #13** 2022-01-10 15:27**MOT test number** 312748664618**Result** ✓ Passed**MOT #12** 2021-01-25 10:35**MOT test number** 436238452524**Result** ✓ Passed**MOT #11** 2021-01-15 15:56**MOT test number** 384838144546**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Exhaust has a major leak of exhaust gases front flexi (6.1.2 (a))**MOT #10** 2020-07-30 10:36**MOT test number** 951418652276**Result** ✓ Passed**Advice** Minor exhaust blow from flexi

**MOT #9** 2020-07-30 07:54**MOT test number** 222269075951**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Minor leak from exhaust flexi

MOT #8 2019-08-03 11:24**MOT test number** 193830161659**Result** ✓ Passed

Advice Advise sweat from gearbox/engine area

MOT #7 2019-08-02 09:15**MOT test number** 703280375111**Result** ✗ Failed

Advice Nearside Rear tyre sidewalls badly perished

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge on legal limit 175/65-15 82t (5.2.3 (e))

Advice Advise sweat from gearbox/engine area

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #6 2018-09-04 13:54**MOT test number** 357533790149**Result** ✓ Passed

**MOT #5** 2018-08-30 16:21**MOT test number** 210503487927**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2018-03-24 10:44**MOT test number** 272072837844**Result** ✓ Passed**MOT #3** 2017-03-11 10:33**MOT test number** 188852614500**Result** ✓ Passed**MOT #2** 2016-03-26 11:24**MOT test number** 590536614568**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2015-03-19 15:14**MOT test number** 119708275019**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
24 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 SA12KLF
Plate since	2019-09-28
Current registration	 SA12KLF
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-24
Last registration	2024-01-24
Complete history	See info



Registration #1	2012-03-24	16 mi
Registration #2	2015-03-19	25.011 mi
Registration #3	2016-03-26	31.147 mi
Registration #4	2017-03-11	36.740 mi
Registration #5	2018-03-24	43.331 mi
Registration #6	2018-08-30	45.798 mi
Registration #7	2018-09-04	45.801 mi
Registration #8	2019-08-02	52.378 mi
Registration #9	2019-08-03	52.378 mi
Registration #10	2020-07-30	56.904 mi
Registration #11	2020-08-20	59.377 mi
Registration #12	2020-09-20	59.377 mi
Registration #13	2020-10-20	59.377 mi
Registration #14	2020-11-20	59.377 mi
Registration #15	2020-12-20	59.377 mi
Registration #16	2021-01-20	59.377 mi
Registration #17	2021-02-20	59.377 mi
Registration #18	2021-03-20	59.377 mi
Registration #19	2021-04-20	59.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A024J283