



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-04-27
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #13 2023-11-21 16:12

MOT test number 290175377405

Result ✓ Passed

Next expiry date 2024-11-25

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Power steering pipe/hose slightly corroded from steering rack to pump (2.1.5 (g) (i))

MOT #12 2023-11-21 11:34

MOT test number 601748922683

Result ✗ Failed

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge bald in places (5.2.3 (e))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Power steering pipe/hose slightly corroded from steering rack to pump (2.1.5 (g) (i))

MOT #11 2022-11-24 10:26

MOT test number 159437846692

Result ✓ Passed

**MOT #10** 2021-11-24 15:50**MOT test number** 148342175083**Result** ✓ Passed**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2020-11-17 11:28**MOT test number** 668784154267**Result** ✓ Passed**MOT #8** 2019-11-21 13:57**MOT test number** 771635628353**Result** ✓ Passed**MOT #7** 2018-11-23 16:25**MOT test number** 550617925644**Result** ✓ Passed**MOT #6** 2017-11-24 16:23**MOT test number** 121099312932**Result** ✓ Passed**Advice** Engine covers and undertrays fitted obscuring some testable components

**MOT #5** 2017-11-24 12:55**MOT test number** 102842043040**Result** ✗ Failed**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Engine covers and undertrays fitted obscuring some testable components**MOT #4** 2016-11-23 11:31**MOT test number** 999511331553**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Engine covers & undertrays fitted**Advice** Nearside Rear Tyre worn close to the legal limit 2.6mm (4.1.E.1)**MOT #3** 2015-11-23 13:08**MOT test number** 161312172996**Result** ✓ Passed**Advice** Engine covers and undertrays fitted**MOT #2** 2014-11-17 15:52**MOT test number** 967751724374**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #1	2014-11-17 09:32
MOT test number	455921924454
Result	✗ Failed
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK61LXG
Plate since	2024-03-28
Current registration	AK61LXG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-25
Last registration	2023-11-21
Complete history	See info



Registration #1	2011-11-25	8 mi
Registration #2	2014-11-17	16.896 mi
Registration #3	2014-11-17	16.904 mi
Registration #4	2015-11-23	21.640 mi
Registration #5	2016-11-23	24.536 mi
Registration #6	2017-11-24	27.459 mi
Registration #7	2017-11-24	27.467 mi
Registration #8	2018-11-23	31.080 mi
Registration #9	2019-11-23	35.192 mi
Registration #10	2020-11-23	39.304 mi
Registration #11	2021-11-23	43.416 mi
Registration #12	2022-11-23	47.528 mi
Registration #13	2023-11-23	51.640 mi
Registration #14	2024-11-23	55.752 mi
Registration #15	2025-11-23	59.864 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212