



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2900 L2H1 CDTi P/V SPORTIVE
Colour	White
Year of manufacture	2016
Top speed	107 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G





MOT history

MOT expiry date	2025-01-13
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #8 2024-01-12 17:10

MOT test number 634115999647

Result ✓ Passed

Next expiry date 2025-01-13

Minor Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Coolant level low**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2023-01-11 10:38

MOT test number 961520953354

Result ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))

MOT #6 2022-01-14 11:20

MOT test number 505939744819

Result ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2022-01-10 15:25**MOT test number** 163490442986**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #4** 2021-01-11 20:03**MOT test number** 500905621679**Result** ✓ Passed**MOT #3** 2020-04-16 10:44**MOT test number** 685848142183**Result** ✓ Passed**MOT #2** 2019-04-05 11:31**MOT test number** 642955573552**Result** ✓ Passed**MOT #1** 2019-04-05 08:24**MOT test number** 480087912979**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	EY16ODJ
Plate since	2019-03-28
Current registration	EY16ODJ
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-04-20
Last registration	2024-01-12
Complete history	See info



Registration #1	2016-04-20	13 mi
Registration #2	2019-04-05	46.793 mi
Registration #3	2019-04-05	46.793 mi
Registration #4	2020-04-16	63.895 mi
Registration #5	2021-01-11	70.324 mi
Registration #6	2022-01-20	75.277 mi
Registration #7	2022-01-20	75.277 mi
Registration #8	2023-01-20	75.277 mi
Registration #9	2024-01-12	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1956 mm
Height	1968 mm
Length	5398 mm
Wheel base	3498 mm
Kerb weight	1729 kg
Max. allowed weight	3010 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	R9M MB - C074592LWU