



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT HDI 110 P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 2

Date	2022-01-22
Pictures	34
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-09
Pictures	34
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #26	2023-01-26 09:14
MOT test number	281552685242
Result	✓ Passed
Next expiry date	2024-01-25

MOT #25	2023-01-17 09:15
MOT test number	895599130313
Result	✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill (5.3.6 (a) (i))

Advice Offside Rear Nail in tyre

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill (5.3.6 (a) (i))

Fail Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #24	2022-01-21 16:36
MOT test number	822615549745
Result	✓ Passed

**MOT #23** 2022-01-21 16:36**MOT test number** 651856109665**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Side repeater incorrect colour (4.4.3 (a))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Offside Side repeater incorrect colour (4.4.3 (a))**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #22** 2021-01-11 08:40**MOT test number** 278188632892**Result** ✓ Passed**MOT #21** 2019-02-06 08:01**MOT test number** 295671762948**Result** ✓ Passed**MOT #20** 2019-02-06 08:01**MOT test number** 694686305911**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #19** 2018-02-02 09:41**MOT test number** 260294962457**Result** ✓ Passed**Advice** Offside Front Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #18** 2017-02-04 14:30**MOT test number** 871579384161**Result** ✓ Passed**Advice** N/s mirror deteriorating**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #17** 2016-02-12 16:50**MOT test number** 323460617471**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Exhaust tail pipe corroding**MOT #16** 2016-02-12 12:57**MOT test number** 153313886002**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Exhaust tail pipe corroding**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #15** 2015-02-14 09:56**MOT test number** 745995345009**Result** ✓ Passed**Notice** Both side repeaters faded

**MOT #14** 2015-02-14 09:56**MOT test number** 125025745461**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Both side repeaters faded**MOT #13** 2014-02-14 14:47**MOT test number** 459715844001**Result** ✓ Passed**Advice** Side repeater slightly discoloured (1.4.A.2f)**MOT #12** 2013-02-09 09:33**MOT test number** 118630043088**Result** ✓ Passed**Notice** O/s mirror damaged**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #11** 2013-02-09 09:33**MOT test number** 509690143005**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Notice** O/s mirror damaged**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #10** 2012-02-11 12:52**MOT test number** 789372242091**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Rattle from exhaust**MOT #9** 2012-02-11 09:36**MOT test number** 577652842073**Result** ✗ Failed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Rattle from exhaust**Fail** Horn not working (1.6.2a)**MOT #8** 2011-02-19 12:40**MOT test number** 859150551029**Result** ✓ Passed**MOT #7** 2011-02-19 10:03**MOT test number** 536310051026**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2010-03-04 11:40**MOT test number** 124843560409**Result** ✓ Passed

**MOT #5** 2010-03-02 08:56**MOT test number** 311891060065**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front constant velocity joint gaiter split (2.5.C.1a)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

MOT #4 2009-03-07 11:32**MOT test number** 473966069022**Result** ✓ Passed**MOT #3** 2008-03-22 13:09**MOT test number** 904552388044**Result** ✓ Passed**MOT #2** 2007-03-29 13:46**MOT test number** 842438687008**Result** ✓ Passed**MOT #1** 2006-02-03 13:55**MOT test number** 193224736021**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-01-14
Last registration	2023-01-26
Complete history	See info



Registration #1	2005-01-14	12 mi
Registration #2	2006-02-03	14.749 mi
Registration #3	2007-03-29	33.385 mi
Registration #4	2008-03-22	44.533 mi
Registration #5	2009-03-07	53.834 mi
Registration #6	2010-03-02	66.747 mi
Registration #7	2010-03-04	66.782 mi
Registration #8	2011-02-19	77.545 mi
Registration #9	2011-02-19	77.545 mi
Registration #10	2012-02-11	89.205 mi
Registration #11	2012-02-11	89.205 mi
Registration #12	2013-02-09	100.539 mi
Registration #13	2013-02-09	100.539 mi
Registration #14	2013-02-09	100.539 mi
Registration #15	2013-02-09	100.539 mi
Registration #16	2013-02-09	100.539 mi
Registration #17	2013-02-09	100.539 mi
Registration #18	2013-02-09	100.539 mi
Registration #19	2013-02-09	100.539 mi
Registration #20	2013-02-09	100.539 mi
Registration #21	2013-02-09	100.539 mi
Registration #22	2013-02-09	100.539 mi
Registration #23	2013-02-09	100.539 mi
Registration #24	2013-02-09	100.539 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2130 mm
Height	1954 mm
Length	4522 mm
Kerb weight	1480 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	DYPY3006107