



PEUGEOT



WG55WRA

report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI SW SE
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg





Internet history

Entry 1

Date	2021-06-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #22	2021-03-19 12:40
MOT test number	870712326765
Result	✓ Passed
Next expiry date	2022-03-18

MOT #21	2019-12-20 11:34
MOT test number	750387106757
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2019-12-20 11:34
MOT test number	335987376797
Result	✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19	2018-12-21 13:13
MOT test number	875457517894
Result	✓ Passed

MOT #18	2018-12-21 10:15
MOT test number	277375459681
Result	✗ Failed

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Front Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))

**MOT #17**

2018-01-03 11:04

MOT test number

549310702814

Result

✓ Passed

Advice Nearside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Possible fuel leak at tank not leaking at time of test**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside door mirror insecure**MOT #16**

2018-01-02 14:30

MOT test number

240515646731

Result

✗ Failed

Advice Nearside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside door mirror insecure**Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Possible fuel leak at tank not leaking at time of test**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**MOT #15**

2016-12-16 11:31

MOT test number

360766640330

Result

✓ Passed

Advice Possible fuel leak at tank when full not leaking at time of test**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

**MOT #14**

2016-12-15 09:13

MOT test number

352125599784

Result**✗ Failed****Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Possible fuel leak at tank when full not leaking at time of test**Fail** Horn not working (1.6.2a)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #13**

2015-12-30 14:17

MOT test number

153154103487

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit on both edges ADVISE TO REPLACE (4.1.E.1)**Advice** Possible fuel leak from tank when full not leaking at time of test**Advice** Rear wiper split**Advice** Offside Rear Tyre worn close to the legal limit both edges ADVISE TO REPLACE (4.1.E.1)

**MOT #12**

2015-12-23 16:46

MOT test number

915186121705

Result**✗ Failed**

- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Possible fuel leak from tank when full not leaking at time of test
- Fail** Brake pedal anti-slip provision missing (3.3.A.1b)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Front Brakes imbalanced across an axle 33% o/s low (3.7.B.5b)
- Advice** Rear wiper split
- Advice** Offside Rear Tyre worn close to the legal limit both edges ADVISE TO REPLACE (4.1.E.1)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit on both edges ADVISE TO REPLACE (4.1.E.1)



MOT #112014-12-03 12:56

MOT test number607967134366

Result		✓ Passed
Notice	Both front tyres worn slightly on the edges	
Notice	Fuel tank damp	
Notice	N/s rear tyre worn slightly on the edges	
Notice	Slight play in the steering rack	
Notice	O/s mirror loose	
Notice	O/s rear tyre worn on the outer edge	
Notice	Slight oil leak	

**MOT #10**

2014-12-03 09:42

MOT test number

376937634303

Result**✗ Failed**

- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Fuel tank damp
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** N/s rear tyre worn slightly on the edges
- Notice** Slight play in the steering rack
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** O/s mirror loose
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Notice** O/s rear tyre worn on the outer edge
- Notice** Slight oil leak
- Fail** Nearside Headlamp aim too high (1.8)
- Notice** Both front tyres worn slightly on the edges

MOT #9

2013-12-03 15:05

MOT test number

206947133386

Result**✓ Passed**

**MOT #8**

2013-12-03 10:13

MOT test number

313258511605

Result

✗ Failed

- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #7

2012-12-05 13:04

MOT test number

697660842323

Result

✓ Passed

- Advice** Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #6

2011-12-13 11:00

MOT test number

586787041354

Result

✓ Passed

- Notice** Rear discs corroded on inside edge

MOT #5

2010-12-15 16:11

MOT test number

444339540466

Result

✓ Passed



MOT #4	2010-12-14 17:00
MOT test number	520188340346
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Stop lamp not working (1.2.1b)
Fail	Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Fail	Offside Front Front wheel bearing has excessive play (2.5.A.3c)

MOT #3	2009-12-22 09:06
MOT test number	834566159355
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2009-12-15 13:56**MOT test number** 202649949362**Result** ✗ Failed

- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Notice** Odd wheel o/s rear
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Engine management light on
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Headlamp aim too low (1.8)
- Notice** Needs tracking
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2008-11-12 10:49**MOT test number** 453477518354**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-11-28
Last registration	2021-03-19
Complete history	See info



Registration #1	2005-11-28	7 mi
Registration #2	2008-11-12	99.893 mi
Registration #3	2009-12-15	116.636 mi
Registration #4	2009-12-22	116.636 mi
Registration #5	2010-12-14	125.516 mi
Registration #6	2010-12-15	125.516 mi
Registration #7	2011-12-13	134.615 mi
Registration #8	2012-12-05	148.231 mi
Registration #9	2013-12-03	157.272 mi
Registration #10	2013-12-03	157.278 mi
Registration #11	2014-12-03	167.590 mi
Registration #12	2014-12-03	167.590 mi
Registration #13	2015-12-03	167.590 mi
Registration #14	2015-12-03	167.590 mi
Registration #15	2015-12-03	167.590 mi
Registration #16	2015-12-03	167.590 mi
Registration #17	2015-12-03	167.590 mi
Registration #18	2015-12-03	167.590 mi
Registration #19	2015-12-03	167.590 mi
Registration #20	2015-12-03	167.590 mi
Registration #21	2015-12-03	167.590 mi
Registration #22	2015-12-03	167.590 mi
Registration #23	2015-12-03	167.590 mi
Registration #24	2015-12-03	167.590 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1471 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1623 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	DYTE4104873
---------------	-------------