



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | VOLKSWAGEN |
| Model | CADDY C20 TDI HIGHLINE |
| Colour | Grey |
| Year of manufacture | 2019 |
| Top speed | 107 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------------|
| Power | 75 kW / 102 HP / 101 BHP |
| Max. torque | 250 Nm at 1.300 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-05-26 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-04 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 1 |

MOT #4 2024-03-26 16:56

MOT test number 276421815091

Result ✓ Passed

Next expiry date 2025-04-04

Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre on 3mm, and wearing on inner edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Tyre on 3mm (5.2.3 (e))

MOT #3 2024-03-26 11:50

MOT test number 178719883910

Result ✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre on 3mm, and wearing on inner edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Tyre on 3mm (5.2.3 (e))

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #2 2023-03-24 09:17

MOT test number 633656827408

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



| | |
|-----------------|---|
| MOT #1 | 2022-04-05 12:42 |
| MOT test number | 604302094994 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
4 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 4 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 7 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-01-25 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-01-25 | 13 mi |
| Registration #2 | 2022-04-05 | 14.788 mi |
| Registration #3 | 2023-05-20 | 25,377 mi |
| Registration #4 | 2023-05-20 | 25,377 mi |
| Registration #5 | 2023-05-20 | 25,377 mi |
| Registration #6 | 2023-05-20 | 25,377 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 78% |
| Pedestrian | 58% |
| Safety systems | 68% |
| Overall rating | 74% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2062 mm |
| Height | 1823 mm |
| Length | 4408 mm |
| Wheel base | 2682 mm |
| Kerb weight | 1496 kg |
| Max. allowed weight | 2141 kg |

Additional information

| | |
|--------------------|------|
| Fuel tank capacity | 55 l |
| Number of seats | 2 |
| Number of axles | 2 |

