





General information

Make	KIA
Model	CEED 1
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-21
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #13	2024-02-20 17:15
MOT test number	210885026781
Result	✓ Passed
Next expiry date	2025-02-21

MOT #12	2024-02-20 12:59	
MOT test number	352341631794	
Result	🗙 Failed	
Fail Nearside Front Lower Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))		
Minor Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))		

MOT #11	2023-02-22 16:24
MOT test number	693351317936
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessi bush unbonding (5.3.4 (a) (i))	ve movement front
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush unbonding (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #10	2023-02-21 10:21
MOT test number	946362840596
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailOffside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents(5.3.4 (b) (ii))	the ingress of dirt
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excess bush unbonding (5.3.4 (a) (i))	ive movement front
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
FailNearside Front Lower Anti-roll bar linkage ball joint dust cover no longer preven(5.3.4 (b) (ii))	ts the ingress of dirt
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive bush unbonding (5.3.4 (a) (i))	e movement front
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MOT #9	2022-02-22 12:49
MOT test number	380222382228

	300222302220
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive bush (5.3.4 (a) (i))	ve movement front
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excess bush (5.3.4 (a) (i))	sive movement front

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))





MOT #8	2022-02-21 15:53	
MOT test number	803862523087	
Result	🗙 Failed	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in exe bush (5.3.4 (a) (i))	cessive movement front	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))		
Advice Offside Front Suspension arm pin or bush worn but not resulting in exce bush (5.3.4 (a) (i))	essive movement front	

MOT #7	2021-01-16 10:43
MOT test number	407847115915
Result	✓ Passed

MOT #6		2020-02-04 15:10
MOT test n	number	250892459220
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exce	ssive movement (5.3.4 (a)
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exc	cessive movement (5.3.4

MOT #5		2019-02-01 09:04
MOT test	number	872505650631
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4	2018-02-08 12:16
MOT test number	679926896770
Result	✓ Passed
MOT #3	2017-02-15 15:45
MOT test number	827950660823
Result	✓ Passed
MOT #2	2016-06-09 08:54
MOT test number	839048100209
Result	✓ Passed
Advice Offside Front Lower Suspension arm rubber bush deteriorated but movement (2.4.G.2)	not resulting in excessive
Advice Nearside Front Lower Suspension arm rubber bush deteriorated be movement (2.4.G.2)	ut not resulting in excessive
MOT #1	2015-06-08 09:22

MOT #1	2015-06-08 09:22
MOT test number	767169655136
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 21 February 2025
Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lampe
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-30
Last registration	2024-02-20
Complete history	See info



Registration #1	2012-06-30	17 mi
Registration #2	2015-06-08	9.319 mi
Registration #3	2016-06-09	12.653 mi
Registration #4	2017-02-15	15.874 mi
Registration #5	2018-02-08	23.679 mi
Registration #6	2019-02-01	30.150 mi
Registration #7	2020-02-04	37.263 mi
Registration #8	2021-01-16	41.286 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 esi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
S0569	

Safety ratings

Number of seats

Number of axles

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1263 kg
Max. allowed weight	1710 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5

5

2