



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	Blue
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-18
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	27
Total items failed	0

MOT #13	2023-09-01 12:09
MOT test number	476257649134
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2023-08-30 11:44
MOT test number	856399432609
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11	2022-09-01 11:22
MOT test number	204751710452
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2022-08-11 11:57

MOT test number

662857026048

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9**

2021-07-30 17:29

MOT test number

275553504310

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #8**

2021-07-29 09:31

MOT test number

156729285290

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #7**

2020-08-05 09:50

MOT test number

530058054259

Result**✓ Passed**

**MOT #6** 2019-08-15 12:27**MOT test number** 594292274646**Result** ✓ Passed**MOT #5** 2019-08-15 08:52**MOT test number** 382213180594**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2018-07-31 10:46**MOT test number** 758669211029**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge cracking (5.2.3 (e))**MOT #3** 2017-08-04 12:02**MOT test number** 191220543355**Result** ✓ Passed**MOT #2** 2016-06-17 12:48**MOT test number** 567873983538**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-06-19 13:46
MOT test number	239450075153
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-22
Last registration	2023-09-01
Complete history	See info



Registration #1	2012-06-22	19 mi
Registration #2	2015-06-19	35.591 mi
Registration #3	2016-06-17	38.698 mi
Registration #4	2017-08-04	43.694 mi
Registration #5	2018-07-31	49.493 mi
Registration #6	2019-08-15	61.363 mi
Registration #7	2019-08-15	61.363 mi
Registration #8	2020-08-05	72.662 mi
Registration #9	2020-08-05	72.662 mi
Registration #10	2020-08-05	72.662 mi
Registration #11	2020-08-05	72.662 mi
Registration #12	2020-08-05	72.662 mi
Registration #13	2020-08-05	72.662 mi
Registration #14	2020-08-05	72.662 mi
Registration #15	2020-08-05	72.662 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Number of axles	2
Engine number	G4FDBU724579