



Mercedes-Benz



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | MERCEDES-BENZ |
| Model | CLK C240 AVANTGARDE SE |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 140 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 170 BHP |
| Max. torque | 240 Nm at 4.500 rpm |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 17.1 mpg |
| Consumption extra urban | 34.0 mpg |
| Consumption combined | 25.2 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-06 |
| Pictures | 37 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #22 | 2021-07-03 14:36 |
| MOT test number | 867157404048 |
| Result | ✓ Passed |
| Next expiry date | 2022-07-02 |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

| | |
|------------------------|--|
| MOT #21 | 2021-06-28 15:11 |
| MOT test number | 132655070160 |
| Result | ✗ Failed |
| MAJOR | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| MAJOR | Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |

| | |
|------------------------|------------------|
| MOT #20 | 2020-06-05 15:06 |
| MOT test number | 260998622758 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #19 | 2020-06-01 09:19 |
| MOT test number | 863176781232 |
| Result | ✗ Failed |
| MAJOR | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) |



MOT #18

2018-11-20 10:00

MOT test number

974717621563

| Result | | ✓ Passed |
|--------|--|----------|
| Advice | Nearside Rear Coil spring corroded and offside rear (5.3.1 (b) (i)) | |
| Minor | Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |
| Advice | Nearside Front Direction indicator slightly discoloured (4.4.3 (a)) | |
| Advice | Engine covers and undertrays fitted preventing full inspection | |
| Advice | Front Brake pipe corroded, covered in grease or other material to rear hoses x 2 (1.1.11 (c)) | |
| Minor | Nearside Headlamp lens slightly defective and offside (4.1.1 (b) (i)) | |
| Advice | O/s mirror discoloured | |
| Advice | Nearside Front Brake pipe corroded, covered in grease or other material and offside front (1.1.11 (c)) | |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and offside front (1.1.14 (a) (ii)) | |

**MOT #17**

2018-11-08 09:44

MOT test number

707608446190

Result**✗ Failed**

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake pipe corroded, covered in grease or other material to rear hoses x 2 (1.1.11 (c))
- Advice** Engine covers and undertrays fitted preventing full inspection
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and offside front (1.1.14 (a) (ii))
- DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Minor** Nearside Headlamp lens slightly defective and offside (4.1.1 (b) (i))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material and offside front (1.1.11 (c))
- Advice** O/s mirror discoloured
- Advice** Nearside Rear Coil spring corroded and offside rear (5.3.1 (b) (i))
- DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #16

2017-09-28 08:59

MOT test number

424127328036

Result**✓ Passed****MOT #15**

2017-09-20 16:04

MOT test number

787202586584

Result**✗ Failed**

- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #14** 2016-09-16 10:46**MOT test number** 462251961826**Result** ✓ Passed**MOT #13** 2015-09-30 13:33**MOT test number** 163509093611**Result** ✓ Passed**MOT #12** 2015-09-28 08:52**MOT test number** 587940313882**Result** ✗ Failed**Fail** Offside Front Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Suspension arm has excessive play in a pin/bush rear bush in dog leg lower arm (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #11** 2014-10-21 12:50**MOT test number** 809374794276**Result** ✓ Passed**MOT #10** 2014-10-20 16:25**MOT test number** 605253794261**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #9** 2013-12-09 10:32**MOT test number** 377403243326**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #8** 2013-12-04 16:41**MOT test number** 756378933319**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Oil leak**MOT #7** 2012-10-10 12:46**MOT test number** 228654382255**Result** ✓ Passed**MOT #6** 2012-10-10 09:30**MOT test number** 248964482265**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



| | |
|--|------------------|
| MOT #5 | 2011-07-27 13:32 |
| MOT test number | 358038301469 |
| Result | ✓ Passed |
| MOT #4 | 2010-07-28 12:09 |
| MOT test number | 352709200466 |
| Result | ✓ Passed |
| MOT #3 | 2009-01-09 15:50 |
| MOT test number | 862079709062 |
| Result | ✓ Passed |
| MOT #2 | 2007-12-06 09:07 |
| MOT test number | 451080547361 |
| Result | ✓ Passed |
| MOT #1 | 2006-11-27 14:29 |
| MOT test number | 942281336316 |
| Result | ✓ Passed |
| <div>Notice Child seat fitted not allowing full inspection of adult belt</div> | |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|----------------|------------|
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXX | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2023-03-29 |
| Current registration |  XXXXXX |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2003-08-13 |
| Last registration | 2021-07-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-08-13 | 21 mi |
| Registration #2 | 2006-11-27 | 27.002 mi |
| Registration #3 | 2007-12-06 | 29.684 mi |
| Registration #4 | 2009-01-09 | 32.695 mi |
| Registration #5 | 2010-07-28 | 35.711 mi |
| Registration #6 | 2011-07-27 | 41.457 mi |
| Registration #7 | 2012-10-10 | 53.891 mi |
| Registration #8 | 2012-10-10 | 53.892 mi |
| Registration #9 | 2013-12-04 | 57.198 mi |
| Registration #10 | 2013-12-09 | 57.198 mi |
| Registration #11 | 2014-10-20 | 60.323 mi |
| Registration #12 | 2014-10-21 | 60.325 mi |
| Registration #13 | 2015-05-20 | 65.337 mi |
| Registration #14 | 2015-05-20 | 65.337 mi |
| Registration #15 | 2015-05-20 | 65.337 mi |
| Registration #16 | 2015-05-20 | 65.337 mi |
| Registration #17 | 2015-05-20 | 65.337 mi |
| Registration #18 | 2015-05-20 | 65.337 mi |
| Registration #19 | 2015-05-20 | 65.337 mi |
| Registration #20 | 2015-05-20 | 65.337 mi |
| Registration #21 | 2015-05-20 | 65.337 mi |
| Registration #22 | 2015-05-20 | 65.337 mi |
| Registration #23 | 2015-05-20 | 65.337 mi |
| Registration #24 | 2015-05-20 | 65.337 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|-------------|---------|
| Width | 1956 mm |
| Height | 1473 mm |
| Length | 4546 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1585 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 11291231582751 |