



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 105BHP
Colour	Beige
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-04
Pictures	42
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #14	2023-09-20 07:54
MOT test number	951364293628
Result	✓ Passed
Next expiry date	2024-09-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-09-22 09:36
MOT test number	592732655576
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2021-09-10 09:50
MOT test number	577145913466
Result	✓ Passed

MOT #11	2020-09-21 11:03
MOT test number	242123870542
Result	✓ Passed

**MOT #10** 2019-09-17 09:34**MOT test number** 635827040195**Result** ✓ Passed

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive both outer sills (5.3.6 (a) (i))

MOT #9 2018-09-18 10:13**MOT test number** 390239263009**Result** ✓ Passed**MOT #8** 2017-09-18 09:55**MOT test number** 409890298964**Result** ✓ Passed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' has a stonechip (8.3.1d)

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened o/s & n/s inner faces (3.5.1i)

MOT #7 2016-09-12 09:56**MOT test number** 311401943967**Result** ✓ Passed

Advice Offside Front windscreen wiper slightly deteriorated

Advice Undertrays fitted

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' lower screen has a stonechip (8.3.1d)

MOT #6 2015-09-22 11:29**MOT test number** 756718512224**Result** ✓ Passed

**MOT #5** 2015-09-15 10:06**MOT test number** 236758310371**Result** ✗ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner & outer sidewall has several lumps (4.1.D.1b)

Fail Nearside Front Road wheel distorted inner & outer rim damaged (4.2.A.1a)

MOT #4 2014-09-17 09:56**MOT test number** 538460664248**Result** ✓ Passed

Notice O/s/front lower windscreen has damage.

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Rear silencer outer skin corroded

MOT #3 2013-09-23 10:20**MOT test number** 868116863225**Result** ✓ Passed**MOT #2** 2012-10-01 10:25**MOT test number** 325385872409**Result** ✓ Passed**MOT #1** 2011-10-15 09:14**MOT test number** 708048781247**Result** ✓ Passed

Notice N/s front washer jet spray poor

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KN58NFU
Plate since	2019-06-29
Current registration	 KN58NFU
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-10-22
Last registration	2023-09-20
Complete history	See info



Registration #1	2008-10-22	12 mi
Registration #2	2011-10-15	20.071 mi
Registration #3	2012-10-01	24.681 mi
Registration #4	2013-09-23	29.220 mi
Registration #5	2014-09-17	32.856 mi
Registration #6	2015-09-15	37.054 mi
Registration #7	2015-09-22	37.154 mi
Registration #8	2016-09-12	40.259 mi
Registration #9	2016-09-20	40.259 mi
Registration #10	2016-09-20	40.259 mi
Registration #11	2016-09-20	40.259 mi
Registration #12	2016-09-20	40.259 mi
Registration #13	2016-09-20	40.259 mi
Registration #14	2016-09-20	40.259 mi
Registration #15	2016-09-20	40.259 mi
Registration #16	2016-09-20	40.259 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1460 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BSW 017167