



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO ACTIVE
Colour	Black
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-12-04
Pictures	28
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-25
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	42
Total items failed	5

MOT #14	2023-05-20 09:23
MOT test number	227202140145
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #13	2023-05-15 12:03
MOT test number	332741628790
Result	✗ Failed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
MAJOR	Offside Parking brake inoperative on one side very low performance (1.4.1 (a))
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
DANGEROUS	Stop lamp(s) all not working (4.3.1 (a) (iii))

**MOT #12**

2022-05-16 13:20

MOT test number

688437253198

Result

✓ Passed

- Advice** Front Lower Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Shock absorbers has slight external damage to the casing both side (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))

MOT #11

2022-05-16 13:20

MOT test number

892952969494

Result

✗ Failed

- Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))
- Advice** Front Lower Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing both side (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2021-05-26 11:19

MOT test number

340563550139

Result

✓ Passed

Advice Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened surface rust (5.3.3 (b) (i))**MOT #9**

2019-02-09 08:56

MOT test number

134104165115

Result

✓ Passed

Advice Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Sub-frame corroded but not seriously weakened both (5.3.3 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2019-02-09 08:56**MOT test number** 861216614454**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Sub-frame corroded but not seriously weakened both (5.3.3 (b) (i))**Advice** Rear Road wheel slightly distorted (5.2.2 (c) (i))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2018-02-20 10:04**MOT test number** 802041164017**Result** ✓ Passed**MOT #6** 2018-02-08 13:21**MOT test number** 625372821761**Result** ✗ Failed**Fail** Headlamp switch faulty (1.7.1)**MOT #5** 2017-08-01 14:39**MOT test number** 933565332245**Result** ✓ Passed**Advice** Shock absorber has slight corrosion to the casing both rear (2.7.2a)

**MOT #4** 2016-08-25 14:10**MOT test number** 645014735375**Result** ✓ Passed**Advice** Both front strut top mounts stiff in operation**Advice** Exhaust corroded**MOT #3** 2015-08-10 09:35**MOT test number** 115142725255**Result** ✓ Passed**MOT #2** 2014-08-15 14:14**MOT test number** 389597624432**Result** ✓ Passed**MOT #1** 2013-08-26 15:29**MOT test number** 799138633207**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear exhaust box slightly corroded**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-29
Last registration	2023-05-20
Complete history	See info



Registration #1	2010-07-29	25 mi
Registration #2	2013-08-26	23.979 mi
Registration #3	2014-08-15	29.355 mi
Registration #4	2015-08-10	35.385 mi
Registration #5	2016-08-25	42.409 mi
Registration #6	2017-08-01	56.601 mi
Registration #7	2018-02-08	61.180 mi
Registration #8	2018-02-20	61.180 mi
Registration #9	2019-05-20	61.180 mi
Registration #10	2020-05-20	61.180 mi
Registration #11	2021-05-20	61.180 mi
Registration #12	2022-05-20	61.180 mi
Registration #13	2023-05-20	61.180 mi
Registration #14	2024-03-29	61.180 mi
Registration #15	2024-03-29	61.180 mi
Registration #16	2024-03-29	61.180 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116