





### General information

| Make                | VOLVO                     |  |
|---------------------|---------------------------|--|
| Model               | V60 D5 TWIN ENGINE SE NAV |  |
| Colour              | Blue                      |  |
| Year of manufacture | 2017                      |  |
| Top speed           | 130 mph                   |  |
| 0 - 60 mph          | 6.7 seconds               |  |
| Gearbox             | 6 speed automatic         |  |

### Engine & fuel consumption

| Power                | 231 BHP             |
|----------------------|---------------------|
| Max. torque          | 620 Nm at 1.500 rpm |
| Engine capacity      | 2.400 cc            |
| Cylinders            | 5                   |
| Fuel type            | Electric / Diesel   |
| Consumption combined | 156.9 mpg           |
| CO2 emission         | 48 g/km             |
| CO2 label            | А                   |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2022-03-12  |
| Pictures         | 1           |
| Listing price    | View report |



source: cargurus.co.uk



### MOT history

| MOT expiry date    | 2025-04-27 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 1          |
| Total items failed | 2          |

| MOT #5           | 2024-04-25 11:07 |
|------------------|------------------|
| MOT test number  | 771246622573     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-04-27       |

| MOT #4          | 2023-04-04 13:25 |
|-----------------|------------------|
| MOT test number | 803830990257     |
| Result          | ✓ Passed         |

| MOT #3          | 2022-04-28 09:04 |
|-----------------|------------------|
| MOT test number | 395221513986     |
| Result          | ✓ Passed         |

| MOT #2  | 2022-04-21 09:05          |
|---|---------------------------|
| MOT test number   | 321391524349              |
| Result  | 🗙 Failed                  |
| <b>Fail</b> Offside Front Windscreen washer jets misaligned and not providing sufficien (3.5 (a)) | t fluid to the windscreen |
| Fail Offside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))                      |                           |
| Minor Front Windscreen wiper blade defective starting to smear screen (3.4 (b)                    | (i))                      |





| MOT #1          | 2020-10-21 11:25 |
|-----------------|------------------|
| MOT test number | 755328082169     |
| Result          | ✓ Passed         |



Tax & MOT check

| √<br>Taxed               | √<br>MOT                  |  |
|--------------------------|---------------------------|--|
| Tax due:<br>1 April 2025 | Expires:<br>27 April 2025 |  |
| Tax status               | Valid until 1 April       |  |
| Days left                | 337                       |  |
| MOT expiry date          | 27 April 2025             |  |
| Full MOT history         | See MOT history           |  |

### Tax calculation

| Vehicle class                 | 59         |
|-------------------------------|------------|
| Band                          | В          |
| First licence fee (12 months) | £ 0,00,-   |
| Standard rate (12 months)     | £ 170,00,- |
| Standard rate (6 months)      | £ 93,50,-  |
| Premium rate (12 months)      | £ 560,00,- |
| Premium rate (6 months)       | £ 308,00,- |





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     | FERM        |
| Category | <br>A PLANE |
| Туре     |             |
| Damage 2 | AMPLE       |
| Damage 2 | E Stand     |
| Date     | *           |
| Category | <br>ante.   |
| Туре     |             |

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******   |             |
|--|-------------|
| ***********  |             |
| *******  |             |
| *******  |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates. |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  | More info > |





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2017-10-09 |
| Last registration          | 2024-04-25 |
| Complete history           | See info   |



| Registration #1 | 2017-10-09 | 17 mi      |
|-----------------|------------|------------|
| Registration #2 | 2020-10-21 | 46.909 mi  |
| Registration #3 |            | 11.777 mi  |
| Registration #4 | 2022-04-21 | 60.805 mi  |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 mi  |

More info >





### Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| \$0482 |                  |
| S0501  |                  |
| \$0566 |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 82%             |
| Pedestrian     | 64%             |
| Safety systems | 100%            |
| Overall rating | 86%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1899 mm          |
| Height                            | 1484 mm          |
| Length                            | 4635 mm          |
| Wheel base                        | 2776 mm          |
| Kerb weight                       | 2024 kg          |
| Max. allowed weight               | 2505 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 45               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11     |

| Number of axles | 2       |
|-----------------|---------|
| Engine number   | 1697128 |