



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-02-23
Pictures	26
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-04-18
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	14
Total items failed	6

MOT #14 2024-04-16 17:00**MOT test number** 384342339146**Result** ✓ Passed**Next expiry date** 2025-04-18**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Cut n/sf tyre outer wall**MOT #13** 2023-04-19 14:59**MOT test number** 884316788795**Result** ✓ Passed**Advice** Suspension arm pin or bush worn but not resulting in excessive movement front and rear (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Shock absorbers has a reduced damping effect front and rear (5.3.2 (d))**Advice** Engine Covers / Under-trays Fitted**MOT #12** 2022-04-13 14:36**MOT test number** 429014004736**Result** ✓ Passed**Advice** Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11** 2021-09-10 14:59**MOT test number** 462047218488**Result** ✓ Passed**MOT #10** 2021-09-09 12:34**MOT test number** 779162949907**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged inner edge (5.2.3 (d) (ii))**MOT #9** 2020-09-17 14:35**MOT test number** 679287081200**Result** ✓ Passed**MOT #8** 2020-09-17 09:11**MOT test number** 639155767319**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Direction indicator with a multiple light source more than 1/2 not functioning door mirror (4.4.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-09-07 09:07**MOT test number** 910108283297**Result** ✓ Passed**MOT #6** 2018-09-04 11:46**MOT test number** 139011352218**Result** ✓ Passed

**MOT #5** 2018-09-04 08:38**MOT test number** 702839012978**Result** ✗ Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Various cuts along tread. (5.2.3 (d) (i))

MOT #4 2017-09-14 13:37**MOT test number** 781985321477**Result** ✓ Passed**MOT #3** 2017-09-14 09:52**MOT test number** 745913117679**Result** ✗ Failed

Fail Nearside Rear coil spring broken (2.4.C.1a)

MOT #2 2016-09-07 08:48**MOT test number** 340690057325**Result** ✓ Passed

Advice Emission not detected

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2016-09-05 09:26**MOT test number** 687891749535**Result** ✗ Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure on inside side wall (4.1.D.1b)

Advice Emission not detected



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 MF63PLX
Plate since	2019-03-29
Current registration	 MF63PLX
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-09-20
Last registration	2024-04-16
Complete history	See info



Registration #1	2013-09-20	22 mi
Registration #2	2016-09-05	37.405 mi
Registration #3	2016-09-07	37.485 mi
Registration #4	2017-09-14	55.828 mi
Registration #5	2017-09-14	55.832 mi
Registration #6	2018-09-04	71.358 mi
Registration #7	2018-09-04	71.373 mi
Registration #8	2019-09-07	86.665 mi
Registration #9	2019-09-07	86.665 mi
Registration #10	2019-09-07	86.665 mi
Registration #11	2019-09-07	86.665 mi
Registration #12	2019-09-07	86.665 mi
Registration #13	2019-09-07	86.665 mi
Registration #14	2019-09-07	86.665 mi
Registration #15	2019-09-07	86.665 mi
Registration #16	2019-09-07	86.665 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1542 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1475 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	K9KF452D022666