



RENAULT

PX57GVM

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC
Colour	Red
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg






Internet history

Entry 1

Date	2021-02-04
Pictures	6
Listing price	View report



source: [autoonline.co.uk](#)



MOT history



MOT #19

2022-10-27 12:08

MOT test number

737297576520

Result

✗ Failed

- Advice

Play in steering rack inner joint(s)
- Fail

Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail

Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail

Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail

Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail

Offside Rear Brake cable damaged park brake cable snapped (1.1.15 (a))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail

Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail

Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Non obligatory mirror damaged
- Fail

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail

Exhaust system insecure rear and centre mounts broken (6.1.2 (a))
- Advice

Both rear shock absorber outer casings corroded
- Fail

Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail

Windscreen washer not working (3.5 (a))
- Fail

Nearside Rear Brake cable damaged park brake cable snapped (1.1.15 (a))
- Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Rear Position lamp slightly affected by the operation of another lamp both (4.2.3 (c))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

Fail Electronic parking brake warning indicates a malfunction (1.1.6 (e))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice Nearside rear light unit damaged



MOT #18

2021-11-15 15:47

MOT test number

447786846538

Result		✓ Passed
Advice	Nearside Non obligatory mirror damaged	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened ALL (1.1.14 (a) (ii))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material BOTH (1.1.11 (c))	
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))	
Advice	Nearside Front Nail in tyre	
Advice	Play in steering rack inner joint(s)	
Minor	Nearside Front Tyre obviously under inflated (5.2.3 (l))	

**MOT #17**

2021-11-12 10:13

MOT test number

628323561172

Result**✗ Failed****Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Rear Brake pipe corroded, covered in grease or other material BOTH (1.1.11 (c))

Advice

Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Nearside Non obligatory mirror damaged

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail

Nearside Front Headlamp aim too low (4.1.2 (a))

Advice

Play in steering rack inner joint(s)

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Minor

Nearside Front Tyre obviously under inflated (5.2.3 (l))

Advice

Brake disc worn, pitted or scored, but not seriously weakened ALL (1.1.14 (a) (ii))

Fail

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Nearside Front Nail in tyre

MOT #16

2020-12-21 16:43

MOT test number

500802631313

Result**✓ Passed****Advice**

Non obligatory mirror damaged

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Play in steering rack inner joint(s)

**MOT #15**

2020-12-17 12:34

MOT test number

201998043976

Result**✗ Failed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Non obligatory mirror damaged
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

2019-10-18 10:45

MOT test number

977379327851

Result**✓ Passed**

- Advice** Offside & Nearside rear shock-absorber outer casings slightly corroded
- Advice** Play in steering rack inner joint(s) Offside & Nearside
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside & Nearside rear seatbelt outer casings missing

**MOT #13**

2019-10-17 09:33

MOT test number

474870080765

Result

✗ Failed

Advice Play in steering rack inner joint(s) Offside & Nearside**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside & Nearside rear shock-absorber outer casings slightly corroded**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside & Nearside rear seatbelt outer casings missing**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #12**

2018-10-17 08:47

MOT test number

467777558675

Result

✓ Passed

Advice Passengers seat belt buckle incomplete n/s**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Passengers seat belt buckle incomplete o/s**MOT #11**

2017-10-10 13:14

MOT test number

472297571482

Result

✓ Passed

Advice Nearside Play in steering rack inner joint(s)

**MOT #10**

2017-10-10 09:32

MOT test number

730804930583

Result

✗ Failed

Fail

Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

Nearside Play in steering rack inner joint(s)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

MOT #9

2016-10-11 08:22

MOT test number

132157236990

Result

✓ Passed

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice

Centre rear seat belt buckle stiff to operate

Advice

Play in steering rack inner joint(s)

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice

N/s/r tyre valve perished

MOT #8

2015-10-14 08:53

MOT test number

647592948329

Result

✓ Passed

Advice

Play in steering arm(s)

Advice

O/s/r tyre slightly perished

Advice

N/s/r tyre slightly perished

Advice

N/s/r tyre valve slightly perished

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2015-10-14 08:53**MOT test number** 344967156104**Result** ✗ Failed**Advice** O/s/r tyre slightly perished**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** N/s/r tyre slightly perished**Advice** N/s/r tyre valve slightly perished**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Play in steering arm(s)**MOT #6** 2014-10-10 10:39**MOT test number** 628513484210**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2013-10-14 10:49**MOT test number** 316597583454**Result** ✓ Passed**MOT #4** 2013-08-14 10:06**MOT test number** 848226323280**Result** ✓ Passed



MOT #3	2012-07-19 12:16
MOT test number	468491702234
Result	✓ Passed
MOT #2	2011-08-15 10:07
MOT test number	707697321291
Result	✓ Passed
MOT #1	2010-11-16 17:12
MOT test number	880080820310
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-11-01
Last registration	2022-10-27
Complete history	See info



Registration #1	2007-11-01	21 mi
Registration #2	2010-11-16	10.878 mi
Registration #3	2011-08-15	13.115 mi
Registration #4	2012-07-19	23.795 mi
Registration #5	2013-08-14	37.290 mi
Registration #6	2013-10-14	37.607 mi
Registration #7	2014-10-10	46.839 mi
Registration #8	2015-10-14	54.459 mi
Registration #9	2015-10-14	54.459 mi
Registration #10	2016-10-11	62.040 mi
Registration #11	2016-10-11	62.040 mi
Registration #12	2016-10-11	62.040 mi
Registration #13	2016-10-11	62.040 mi
Registration #14	2016-10-11	62.040 mi
Registration #15	2016-10-11	62.040 mi
Registration #16	2016-10-11	62.040 mi
Registration #17	2016-10-11	62.040 mi
Registration #18	2016-10-11	62.040 mi
Registration #19	2016-10-11	62.040 mi
Registration #20	2016-10-11	62.040 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D042546