



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 R-DESIGN |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 130 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 145 BHP |
| Max. torque | 185 Nm at 4.500 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 27.7 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-06 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-23 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 35 |
| Total items failed | 4 |

| | |
|---------|------------------|
| MOT #13 | 2024-04-24 07:47 |
|---------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 569377231339 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2025-04-23 |
|------------------|------------|

- Advice
- Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice
- Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice
- Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice
- Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2023-01-27 07:10

MOT test number

860286353603

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #11

2023-01-25 07:52

MOT test number

455492817681

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10**

2022-01-21 14:54

MOT test number

798234808821

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**MOT #9**

2021-01-20 12:36

MOT test number

638283730222

Result

✓ Passed

MOT #8

2021-01-13 13:00

MOT test number

696961365432

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #7**

2019-09-27 10:47

MOT test number

933750430945

Result

✓ Passed

**MOT #6** 2018-10-09 09:14**MOT test number** 241923671926**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #5** 2017-09-25 10:19**MOT test number** 763375031137**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 2.3mm (4.1.E.1)**MOT #4** 2016-10-14 15:12**MOT test number** 457869806698**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 2.8mm (4.1.E.1)**MOT #3** 2016-10-14 11:46**MOT test number** 936898475298**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 2.8mm (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2015-10-07 13:47**MOT test number** 492405201575**Result** ✓ Passed



| | |
|-----------------|---|
| MOT #1 | 2014-10-02 10:35 |
| MOT test number | 218935774271 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
23 April 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 2 |
| MOT expiry date | 23 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2011-10-14 |
| Last registration | 2024-04-24 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-10-14 | 26 mi |
| Registration #2 | 2014-10-02 | 24.521 mi |
| Registration #3 | 2015-10-07 | 31.985 mi |
| Registration #4 | 2016-10-14 | 38.092 mi |
| Registration #5 | 2016-10-14 | 38.092 mi |
| Registration #6 | 2017-09-25 | 42.007 mi |
| Registration #7 | 2018-10-09 | 46.616 mi |
| Registration #8 | 2019-09-27 | 51.676 mi |
| Registration #9 | 2020-05-20 | 55.557 mi |
| Registration #10 | 2020-05-20 | 55.557 mi |
| Registration #11 | 2020-05-20 | 55.557 mi |
| Registration #12 | 2020-05-20 | 55.557 mi |
| Registration #13 | 2020-05-20 | 55.557 mi |
| Registration #14 | 2020-05-20 | 55.557 mi |
| Registration #15 | 2020-05-20 | 55.557 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4252 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1346 kg |
| Max. allowed weight | 1750 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 1045685 |