





report date: 2024-03-28

### General information

Make	MERCEDES
Model	ML ML 270 CDI
Colour	Silver
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	163 BHP
Max. torque	370 Nm at 1.600 rpm
Engine capacity	2.688 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	35.3 mpg
Consumption combined	29.7 mpg
CO2 emission	250 g/km
CO2 label	L



CarCheck.co.uk page 1/14



# Internet history

#### Entry 3

Date	2023-01-21
Pictures	0

Listing price <u>View report</u>

#### source: autotrader.co.uk

### Entry 2

Date	2021-08-27	
Pictures	18	
Listing price	<u>View report</u>	









source: autotrader.co.uk

Entry 1


Date	2021-08-11	
Pictures	18	
Listing price	View report	











source: autotrader.co.uk

CarCheck.co.uk page 2/14



# **MOT** history

MOT expiry date	2023-07-05
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	33
Total items failed	10

MOT #19		2022-07-06 16:00
MOT test	number	967724257421
Result		✓ Passed
Next expi	ry date	2023-07-05
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/14



**MOT #18** 2022-07-04 16:18

**MOT test number** 878425128449

Result × Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Brake performance not tested due to O/S/F Bearing (1.2.1 (g))

Fail Offside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2020-11-26 13:21

**MOT test number** 735792584914

Result \( \sqrt{Passed} \)

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both inner and outer edge (5.2.3 (e))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2019-05-22 10:43

MOT test number 780171943936

**Result** ✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/14



**MOT #15** 2019-05-18 16:58

**MOT test number** 605115675402

**Result** ★ Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2018-04-25 15:54

**MOT test number** 892095158522

Result Passed

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)

**Advice** Brake pipe slightly corroded (3.6.B.2c)

MOT #13 2017-04-14 10:44

MOT test number 645568338073

Advice Anti-roll bar rubber bush deteriorated but not resulting in excessive movement Both front

Advice Brake pad(s) wearing thin Both front and rear (3.5.1g)

**Advice** Brake pipe slightly corroded (3.6.B.2c)

(2.4.G.2)

MOT #12 2016-04-12 12:44

MOT test number 230029281153

CarCheck.co.uk page 5/14



**MOT #11** 2016-04-12 12:02

MOT test number 162315025043

**Result** X Failed

**Fail** Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #10 2015-03-31 08:51

MOT test number 257090095005

**Result** 
✓ Passed

**Notice** Under-trays fitted obscuring some underside components

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Brake pipe slightly corroded (3.6.B.2c)

MOT #9 2014-04-01 16:21

MOT test number 317541094013

Result 

Passed

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #8 2014-04-01 13:47

**MOT test number** 408911994023

**Result** X Failed

**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**Fail** Offside Rear Stop lamp not working (1.2.1b)

**Notice** Under-trays fitted obscuring some underside components

**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

CarCheck.co.uk page 6/14



MOT #7	2013-04-02 17:27
MOT test number	397192793084
Result	<b>✓</b> Passed
MOT #6	2012-04-12 15:27
MOT test number	467603402147
Result	✓ Passed
MOT #5	2011-04-09 13:49
MOT test number	558569791036
Result	✓ Passed
MOT #4	2010-03-30 13:49
MOT test number	152319580080
Result	✓ Passed
Notice O/S/F TYRE AT LEGAL LIMITS.	
MOT #3	2009-04-11 11:38
MOT test number	964551209122
Dogult	4 Daggad

MOT #3	2009-04-11 11:38
MOT test number	964551209122
Result	<b>✓</b> Passed
MOT #2	2008-04-12 11:07
MOT test number	184013108132
Result	<b>✓</b> Passed
MOT #1	2006-11-23 12:30
MOT test number	981507126397
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



#### Tax & MOT check



X MOT

Expired: 5 July 2023

Tax status	Expired at 1 January 2023
Days left	484 days too late
MOT expiry date	5 July 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14




#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
********	
***************************************	
********	
************	
Diate changes	More info >
Plate changes  See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK apz apz
Plate since	
Current registration	NK SIL
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-10-11
Last registration	2022-07-06
Complete history	See info



Registration #1	2002-10-11	17 mi
Registration #2	2006-11-23	21.195 mi
Registration #3	2008-04-12	28.839 mi
Registration #4	2009-04-11	33.874 mi
Registration #5	2010-03-30	38.605 mi
Registration #6	2011-04-09	43.040 mi
Registration #7	2012-04-12	48.864 mi
Registration #8	2013-04-02	54.313 mi
Registration #9	2014-04-01	59.061 mi
Registration #10	2014-04-01	59.061 mi
Registration #11	2015-03-31	62.802 mi
Registration #12	2016-04-12	69.791 mi
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 au
Registration #18		11.777 es
Registration #18 Registration #19		11.777 es
-		11.777 es 11.777 es
Registration #19		11,777 es 11,777 es 11,777 es
Registration #19 Registration #20		11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 13/14



			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	2190 mm
Height	1820 mm
Length	4710 mm
Wheel base	2820 mm
Kerb weight	2115 kg

# Additional information

Fuel tank capacity	83
Fuel delivery	Direct Injection
Number of doors	5
Engine number	61296330215624

CarCheck.co.uk page 14/14