





report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ D V6 PREMIUM LUXURY
Colour	Blue
Year of manufacture	2013
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-07-14

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-30
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #12	2023-07-18 10:58
MOT test number	727733214118
Result	✓ Passed
Next expiry date	2024-07-30

MOT #11		2023-07-14 14:28
MOT test	number	342535617877
Result		× Failed
MAJOR	Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #10	2022-07-29 10:18
MOT test number	139980530385
Result	✓ Passed
Minor Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i) Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #9 2022-07-28 11:09

MOT test number 187457329189

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing extreme edges (5.2.3 (e))

Minor Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing extreme edges (5.2.3 (e))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 245-40-20 (5.2.3 (d) (i))

MOT #8 2021-07-13 12:39

MOT test number 441778039182

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge minimum tread depth of 1.6mm reached (5.2.3 (e))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2020-07-31 11:24

MOT test number 674949744107

Result ✓ Passed

MOT #6 2020-07-30 09:53

MOT test number 502345584196

Result X Failed

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #5		2019-03-19 09:25
MOT test	number	132389992189
Result		✓ Passed
Advice	Nsf tyre sidewall damaged	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #4	2018-04-18 14:20
MOT test number	597863277947
Result	✓ Passed
MOT #3	2017-03-24 08:45
MOT test number	556967906405
Result	✓ Passed
MOT #2	2016-04-11 12:00
MOT test number	603669546328
Result	✓ Passed
MOT #1	2015-08-13 16:39
MOT test number	446475425245
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	
Notice Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	UK JIN
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-27
Last registration	2023-07-18
Complete history	See info



Registration #1	2013-03-27	9 mi
Registration #2	2015-08-13	13.607 mi
Registration #3	2016-04-11	19.218 mi
Registration #4	2017-03-24	21.465 mi
Registration #5	2018-04-18	23.762 mi
Registration #6	2019-03-19	40.143 mi
Registration #7	2020-07-30	51.919 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1894 mm
Height	1448 mm
Length	5122 mm
Wheel base	3157 mm
Kerb weight	1796 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	82 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0790777306DT

CarCheck.co.uk page 11/11