



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX 16V URBAN FOX
Colour	Blue
Year of manufacture	2006
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-02-06
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-23
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	41
Total items failed	2

MOT #19	2023-07-17 10:27
MOT test number	106854295202
Result	✓ Passed
Next expiry date	2024-07-23
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2022-07-20 10:44
MOT test number	619608253712
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Coolant leak

**MOT #17**

2021-07-24 12:28

MOT test number

867696402000

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MOT #16**

2021-07-15 14:34

MOT test number

166045854764

Result

✗ Failed

MAJOR Braking system leaking abs pump (1.1.3 (d))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))

**MOT #15**

2021-06-12 11:06

MOT test number

497567290052

Result**✗ Failed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 185/60r14 (5.2.3 (e))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Hydraulic fluid leaking excessively ABS unit leaking when under pressure. (8.4.1 (a) (i))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #14

2020-06-04 15:40

MOT test number

479514560227

Result**✓ Passed****MOT #13**

2019-06-21 13:59

MOT test number

391528060152

Result**✓ Passed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush. (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 185/60r14 (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2018-05-10 09:24**MOT test number** 916981197623**Result** ✓ Passed**Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #11** 2017-05-22 11:20**MOT test number** 891904982486**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre Both rear tyres are perishing.**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10** 2016-06-20 16:31**MOT test number** 711846179558**Result** ✓ Passed**MOT #9** 2015-11-28 13:33**MOT test number** 874021646235**Result** ✓ Passed**MOT #8** 2014-10-18 12:12**MOT test number** 968041794277**Result** ✓ Passed**MOT #7** 2014-10-04 12:49**MOT test number** 339477774407**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #6** 2013-09-26 15:27**MOT test number** 396209763418**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-10-12 09:40**MOT test number** 347756382476**Result** ✓ Passed**MOT #4** 2011-10-17 12:18**MOT test number** 508590091236**Result** ✓ Passed**MOT #3** 2010-10-21 14:31**MOT test number** 360094590293**Result** ✓ Passed**MOT #2** 2009-10-21 12:56**MOT test number** 433404799230**Result** ✓ Passed**MOT #1** 2009-10-21 12:56**MOT test number** 753374499285**Result** ✗ Failed**Pass with rectification** Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RE56ZHN
Plate since	2024-03-28
Current registration	 RE56ZHN
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-19
Last registration	2023-07-17
Complete history	See info



Registration #1	2006-10-19	28 mi
Registration #2	2009-10-21	12.248 mi
Registration #3	2010-10-21	20.269 mi
Registration #4	2011-10-17	22.799 mi
Registration #5	2012-10-12	25.870 mi
Registration #6	2013-09-26	29.323 mi
Registration #7	2014-10-04	35.579 mi
Registration #8	2014-10-18	36.015 mi
Registration #9	2015-11-28	46.838 mi
Registration #10	2016-06-20	50.656 mi
Registration #11	2016-06-20	50.656 mi
Registration #12	2016-06-20	50.656 mi
Registration #13	2016-06-20	50.656 mi
Registration #14	2016-06-20	50.656 mi
Registration #15	2016-06-20	50.656 mi
Registration #16	2016-06-20	50.656 mi
Registration #17	2016-06-20	50.656 mi
Registration #18	2016-06-20	50.656 mi
Registration #19	2016-06-20	50.656 mi
Registration #20	2016-06-20	50.656 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 024963