





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	2015
Top speed	124 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



**GV15XDY** 

report date: 2024-03-28

## Internet history

## Entry 2

Date	2022-02-01

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-01-31
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-27
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #9		2024-02-28 10:24
MOT test	number	737170635919
Result		✓ Passed
Next exp	iry date	2025-02-27
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Minor Position lamp light intensity obviously reduced both rear outer lamps (4.2.3 (a) (i))		
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)

MOT #8	2024-02-27 15:46
MOT test number	150796558912
Result	<b>×</b> Failed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i	))
Fail Nearside Front Lower Suspension arm pin or bush excessively worn rearmo	est (5.3.4 (a) (i))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Position lamp light intensity obviously reduced both rear outer lamps (4.2.3 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #7 2023-01-27 15:22

MOT test number 714609320079

**Result** ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2022-02-17 16:25

**MOT test number** 820142813960

**Result** ✓ Passed

**MOT #5** 2021-05-19 09:20

**MOT test number** 900653037650

Advice Tyre slightly damaged/cracking or perishing both rears (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2021-05-18 12:21

MOT test number 378727588702

**Result** X Failed

**Advice** Tyre slightly damaged/cracking or perishing both rears (5.2.3 (d) (ii))

Fail Offside Front Lower Suspension arm pin or bush excessively worn rearmost (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2020-05-21 15:00

MOT test number 531456216467

**Result** 
✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



MOT #2 2019-07-10 12:09

MOT test number 112830123887

**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #1** 2018-07-10 12:09

**MOT test number** 720367331051

**Result** ✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	27 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.


#### Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	AIR AIR
Plate since	
	More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-07-28
Last registration	2024-02-28
Complete history	See info



Registration #1	2015-07-28	20 mi
Registration #2	2018-07-10	21.875 mi
Registration #3	2019-07-10	24.555 mi
Registration #4	2020-05-21	26.554 mi
Registration #5	2021-05-18	29.879 mi
Registration #6	2021-05-19	29.879 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2021 mm
Height	1473 mm
Length	4278 mm
Wheel base	2540 mm
Kerb weight	1505 kg
Max. allowed weight	1890 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
CarChock co.uk	nago 12/13

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CUUB018401