



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	White
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-24
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-12
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	43
Total items failed	3

MOT #18	2023-06-13 13:40
MOT test number	371323736865
Result	✓ Passed
Next expiry date	2024-06-12

MOT #17	2023-06-10 09:29
MOT test number	223148907237
Result	✗ Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
MAJOR	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #16	2022-09-10 09:08
MOT test number	890989373972
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front tyres worn on inside edge

**MOT #15**

2021-09-09 11:20

**MOT test number**

739511679905

**Result**

✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2021-08-12 10:28

**MOT test number**

540082156377

**Result**

✗ Failed

- DANGEROUS** Nearside Rear Upper Shock absorbers likely to become detached (5.3.2 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #13** 2020-09-04 16:18**MOT test number** 226363477736**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorated (5.3.4 (a) (i))

**Advice** Hand brake little reserve travel

**Advice** Central brake light part lit

**MOT #12** 2020-09-04 09:23**MOT test number** 262830695188**Result** ✗ Failed

**MAJOR** Windscreen washer provides insufficient washer liquid bottle leaking (3.5 (a))

**Advice** Central brake light part lit

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorated (5.3.4 (a) (i))

**MOT #11** 2019-08-09 18:57**MOT test number** 208664882785**Result** ✓ Passed

**Advice** Nearside Rear Anti-lock braking system wiring damaged but not excessively repaired (1.6 (d))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10** 2018-08-28 11:46**MOT test number** 551428205064**Result** ✓ Passed**Advice** Nearside Rear Anti-lock braking system wiring damaged but not excessively (1.6 (d))**Advice** Offside Rear shocer top bush split**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on boarder line (5.2.3 (e))**MOT #9** 2018-08-28 11:46**MOT test number** 310891999409**Result** ✗ Failed**Advice** Offside Rear shocer top bush split**Advice** Nearside Rear Anti-lock braking system wiring damaged but not excessively (1.6 (d))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on boarder line (5.2.3 (e))**Pass with rectification** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Pass with rectification** Front Registration plate does not conform to the specified requirements (0.1 (d))**MOT #8** 2017-09-01 13:33**MOT test number** 770198516000**Result** ✓ Passed**Advice** Off side front tyre worn on inner edge**MOT #7** 2016-11-29 15:54**MOT test number** 961855285267**Result** ✓ Passed**MOT #6** 2015-11-03 16:40**MOT test number** 599988709040**Result** ✓ Passed

**MOT #5** 2014-12-01 11:20**MOT test number** 879145734303**Result** ✓ Passed**MOT #4** 2013-10-04 12:19**MOT test number** 488187473288**Result** ✓ Passed**MOT #3** 2013-10-03 11:38**MOT test number** 856606973219**Result** ✗ Failed**Notice** Both front strut top binding ,**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2013-03-06 11:55**MOT test number** 645445463032**Result** ✓ Passed**MOT #1** 2012-03-20 09:24**MOT test number** 199660982031**Result** ✓ Passed**Notice** Heavy front tyre wear on inner edges**Notice** Surface corrosion to exhaust**Notice** Slight movement in nearside front anti rollbar link arm ball joints



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
12 June 2024

<b>Tax status</b>	Valid until 1 July
-------------------	--------------------

<b>Days left</b>	64
------------------	----

<b>MOT expiry date</b>	12 June 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-31
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	14 mi
Registration #2	2012-03-20	21.244 mi
Registration #3	2013-03-06	35.254 mi
Registration #4	2013-10-03	40.180 mi
Registration #5	2013-10-04	40.181 mi
Registration #6	2014-12-01	51.581 mi
Registration #7	2015-11-03	60.378 mi
Registration #8	2016-11-29	65.784 mi
Registration #9	2017-09-01	86.127 mi
Registration #10	2018-08-28	101.819 mi
Registration #11	2019-05-29	115.277 mi
Registration #12	2019-05-29	115.277 mi
Registration #13	2019-05-29	115.277 mi
Registration #14	2019-05-29	115.277 mi
Registration #15	2019-05-29	115.277 mi
Registration #16	2019-05-29	115.277 mi
Registration #17	2019-05-29	115.277 mi
Registration #18	2019-05-29	115.277 mi
Registration #19	2019-05-29	115.277 mi
Registration #20	2019-05-29	115.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982300099