



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Grey
Year of manufacture	-
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-29
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-22
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #16	2020-11-05 15:44
MOT test number	166316340545
Result	✓ Passed
Next expiry date	2021-11-04

MOT #15	2020-01-28 14:08
MOT test number	770405739758
Result	✓ Passed
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Front Bumper mountings corroded but not likely to become detached bumper damaged (6.1.4 (a) (i))

MOT #14	2020-01-28 10:13
MOT test number	105096316915
Result	✗ Failed
Advice	Front Bumper mountings corroded but not likely to become detached bumper damaged (6.1.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2019-01-23 12:06
MOT test number	977941667765
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Registration plate insecure but not likely to fall off BROKEN (0.1 (a))
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2019-01-22 12:11**MOT test number** 275173344947**Result** ✗ Failed**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Registration plate insecure but not likely to fall off BROKEN (0.1 (a))**Advice** Nearside Rear Nail in tyre**MOT #11** 2018-01-22 11:09**MOT test number** 695927700472**Result** ✓ Passed**MOT #10** 2017-01-10 14:41**MOT test number** 443920247669**Result** ✓ Passed**Advice** Front bumper damaged**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #9** 2017-01-10 13:29**MOT test number** 659354794990**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Advice** Front bumper damaged**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #8** 2016-12-17 12:35**MOT test number** 307194184953**Result** ✗ Failed**Fail** Offside Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Fail** Nearside Front Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #7** 2015-12-15 10:43**MOT test number** 347229969595**Result** ✓ Passed**Advice** Front wishbones rear bushes deteriorated**MOT #6** 2014-12-16 09:06**MOT test number** 379230854397**Result** ✓ Passed



MOT #5	2014-05-18 12:09
MOT test number	118018534146
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4	2014-05-18 11:15
MOT test number	686008334169
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3	2013-03-21 17:31
MOT test number	685100283038
Result	✓ Passed



MOT #2	2013-03-12 17:20
MOT test number	678251273009
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Notice	Both front tyres have slight cut on outer wall
Fail	Nearside Headlamp aim too low (1.8)
Fail	Offside Front Body has a sharp edge caused by damage (6.1.C.1)
Fail	Offside Side repeater not working (1.4.A.2c)
Fail	Offside Headlamp aim too low (1.8)

MOT #1	2011-11-22 14:42
MOT test number	305756021359
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	KW08SYS
Plate since	2019-06-29
Current registration	KW08SYS
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-08-01
Last registration	2020-11-05
Complete history	See info



Registration #1	2008-08-01	6 mi
Registration #2	2011-11-22	20.359 mi
Registration #3	2013-03-12	30.833 mi
Registration #4	2013-03-21	30.906 mi
Registration #5	2014-05-18	37.780 mi
Registration #6	2014-05-18	37.780 mi
Registration #7	2014-12-16	41.018 mi
Registration #8	2015-12-15	44.398 mi
Registration #9	2016-12-17	47.944 mi
Registration #10	2017-01-10	48.012 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BBM173167