





report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 320 CDI EDITION 10
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.4 mpg
CO2 emission	254 g/km
CO2 label	L



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date 2021-07-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Date 2021-07-02

Pictures 86

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-15
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	32
Total items failed	7

MOT #17		2023-08-29 07:20
MOT test	number	564544868826
Result		✓ Passed
Next expi	ry date	2024-09-15
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #16		2022-09-09 11:46
MOT test	number	883578274424
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/14



Result

BV58UNX

report date: 2024-03-28

Passed

MOT #15 2021-09-16 15:31 MOT test number 204404433156

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14 2020-10-15 14:56

MOT test number 602937237191

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13 2019-09-19 12:52

MOT test number 560462758683

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Both park brake cable outer sleeves corroded

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2019-09-19 12:52

MOT test number 476744771131

Result × Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Both park brake cable outer sleeves corroded

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11		2018-10-17 07:55
MOT test i	number	904432519104
Result		✓ Passed
Advice	Offside Rear Outer Nail in tyre	
Advice	Offside Rear Park brake cable corroded	
Advice	Nearside Rear Park brake cable corroded	

MOT #10	2018-10-16 10:09
MOT test number	517527564677
Result	X Failed
Advice Offside Rear Park brake cable corroded	
Fail Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))	
Advice Offside Rear Outer Nail in tyre	
Advice Nearside Rear Park brake cable corroded	
Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))	

MOT #9	2017-10-09 10:49
MOT test number	491322979044
Result	✓ Passed

MOT #8	2017-10-02 15:12
MOT test number	830728857110
Result	X Failed
Fail Offside Rear coil spring broken (2.4.C.1a)	

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #7 2016-07-04 15:38

MOT test number 413671931490

Result ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-06-01 12:43

MOT test number 488672755101

Result \square Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #5 2015-06-01 12:43

MOT test number 917512755112

Result X Failed

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4 2014-05-23 10:53

MOT test number 246813944485

Result

Passed

MOT #3 2013-05-22 12:42

MOT test number 818672943165

Result

Passed

Notice Nsf tyre has deep cut in tread

CarCheck.co.uk page 6/14



Result

BV58UNX

report date: 2024-03-28

✓ Passed

MOT #2 2012-05-25 08:51

MOT test number 649276642136

MOT #1 2012-02-01 08:16

MOT test number 378732532048

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIL
Plate since	
Current registration	SIK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-30
Last registration	2023-08-29
Complete history	See info



Registration #1	2008-09-30	19 mi
Registration #2	2012-02-01	32.827 mi
Registration #3	2012-05-25	32.865 mi
Registration #4	2013-05-22	54.539 mi
Registration #5	2014-05-23	65.056 mi
Registration #6	2015-06-01	74.214 mi
Registration #7	2016-07-04	80.511 mi
Registration #8	2017-10-02	92.584 mi
Registration #9	2017-10-09	92.674 mi
Registration #10	2018-10-16	100.777 mi
Registration #10 Registration #11	2018-10-16	100.777 mi
-		100.777 mi
Registration #11		100.777 mi
Registration #11 Registration #12		100.777 mi
Registration #11 Registration #12 Registration #13		100.777 mi
Registration #11 Registration #12 Registration #13 Registration #14		100.777 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		100.777 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		100.777 mi

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040672802

CarCheck.co.uk page 14/14