



General information

Make	SUZUKI
Model	GRAND VITARA TD
Colour	Blue
Year of manufacture	2004
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.8 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-02
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	50
Total items failed	11

MOT #24	2023-06-23 14:14
MOT test number	981739719657
Result	✓ Passed
Next expiry date	2024-07-02
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #23	2022-06-08 12:35
MOT test number	659864020622
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view x3 (3.2 (a) (i))

MOT #22	2021-07-03 10:25
MOT test number	267122149695
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Front Windscreen damaged but not adversely affecting driver's view x2 (3.2 (a) (i))

MOT #21	2020-11-24 14:48
MOT test number	369134318965
Result	✓ Passed

**MOT #20**

2019-11-23 09:12

MOT test number

508650779537

Result

✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement d bushes (5.3.4 (a) (i))

MOT #19

2019-11-23 09:12

MOT test number

932799324842

Result

✗ Failed

- Pass with rectification** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement d bushes (5.3.4 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Pass with rectification** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #18

2018-11-13 14:17

MOT test number

980198492987

Result

✓ Passed

- Advice** 3/ o/s outer drive shaft gaiter becoming perished
- Advice** Unable to check outer sills fully due to plastic sill covers
- Advice** 2/ both head lights becoming dull
- Advice** 4/ o/s front tyre worn on outside edge
- Advice** 1/ n/s rear tyre near limits and both rear tyres becoming perished
- Advice** Near side and off side rear sill backings becoming corroded



MOT #17 2018-11-13 08:40

MOT test number 336332922566

Result ✗ Failed

Advice 2/ both head lights becoming dull

Advice 4/ o/s front tyre worn on outside edge

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice 1/ n/s rear tyre near limits and both rear tyres becoming perished

Advice 3/ o/s outer drive shaft gaiter becoming perished

MOT #16 2017-11-22 07:28

MOT test number 320517307716

Result ✓ Passed

Advice 4.slight damage to front windscreen

Advice 1.outer sills not tested due to plastic sill covers fitted at time of test

Advice 3.slight binding on front brakes

Advice 2.off side front outer drive shaft gaiter starting to perish

**MOT #15** 2017-11-21 09:14**MOT test number** 391806605840**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** 1.outer sills not tested due to plastic sill covers fitted at time of test**Advice** 3.slight binding on front brakes**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** 2.off side front outer drive shaft gaiter starting to perish**Advice** 4.slight damage to front windscreen**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #14** 2016-11-18 16:24**MOT test number** 588658838287**Result** ✓ Passed**Advice** Unable to check outer sills fully due to plastic sill covers.**MOT #13** 2016-11-15 09:13**MOT test number** 920667715955**Result** ✗ Failed**Advice** Unable to check outer sills fully due to plastic sill covers.**Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside front brake binding (3.7.B.1)**Fail** Nearside front brake binding (3.7.B.1)

**MOT #12** 2015-11-13 09:12**MOT test number** 844849312614**Result** ✓ Passed

- Advice** 1. Unable to inspect outer sills fully due to plastic sill covers.
- Advice** 3. Damage to front windscreen not in drivers view of the road at time of test.
- Advice** 2. Both front cv gaiters starting to perish.

MOT #11 2014-11-13 08:37**MOT test number** 607417214396**Result** ✓ Passed

- Notice** Plastic sill covers fitted at time of test
- Notice** N/s rear tyre wearing low on outside edge
- Notice** Rear exhaust silencer becoming corroded
- Notice** O/s rear tyre wearing low on inside edge

MOT #10 2013-11-14 10:35**MOT test number** 549788313334**Result** ✓ Passed

- Notice** 4. Nearside front tyre wearing low on outside edge. 5. Slight damage to front windscreen.
- Advice** Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** 1. Exhaust rear box starting to corrode. 2. Unable to inspect outer sills fully due to plastic sill covers. 3. Offside front tyre wearing low on inside edge.

MOT #9 2012-11-15 09:20**MOT test number** 896640422371**Result** ✓ Passed

- Notice** 1. Unable to inspect outer sills fully due to plastic sill covers. 2. Exhaust rear box starting to corrode. 3. Offside front brake disc starting to corrode.



MOT #8	2011-11-23 09:20
MOT test number	389017021357
Result	✓ Passed
Notice	1/ center slencer becoming corroded

MOT #7	2010-10-26 15:02
MOT test number	650589690295
Result	✓ Passed
Notice	1. centre exhaust silencer becomng weak due to corrosion. 2. o/s rear tyre near legal limits.

MOT #6	2010-10-26 10:04
MOT test number	710519790267
Result	✗ Failed
Notice	1. centre exhaust silencer becomng weak due to corrosion. 2. o/s rear tyre near legal limits.
Fail	Rear registration plate obscured (6.3.1d)

MOT #5	2009-11-13 09:10
MOT test number	411017719414
Result	✓ Passed

MOT #4	2009-11-12 17:51
MOT test number	713666219324
Result	✗ Failed
Notice	Rear wiper split
Notice	Blocked washer jet on the drivers side front
Fail	Rear registration plate obscured (6.3.1d)



MOT #3	2008-12-06 09:35
MOT test number	872571648383
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2007-12-13 09:47
MOT test number	624147447335
Result	✓ Passed
Advice	Front brake disc slightly pitted (3.5.1h)

MOT #1	2007-06-07 17:16
MOT test number	430018457121
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
2 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-06-17
Last registration	2023-06-23
Complete history	See info



Registration #1	2004-06-17	22 mi
Registration #2	2007-06-07	11.573 mi
Registration #3	2007-12-13	14.110 mi
Registration #4	2008-12-06	22.903 mi
Registration #5	2009-11-12	30.556 mi
Registration #6	2009-11-13	30.556 mi
Registration #7	2010-10-26	38.161 mi
Registration #8	2010-10-26	38.162 mi
Registration #9	2011-11-23	47.952 mi
Registration #10	2012-11-15	56.670 mi
Registration #11	2013-11-14	66.641 mi
Registration #12	2014-11-13	78.059 mi
Registration #13	2015-11-13	88.981 mi
Registration #14	2016-06-20	88.981 mi
Registration #15	2017-06-20	88.981 mi
Registration #16	2018-06-20	88.981 mi
Registration #17	2019-06-20	88.981 mi
Registration #18	2020-06-20	88.981 mi
Registration #19	2021-06-20	88.981 mi
Registration #20	2022-06-20	88.981 mi
Registration #21	2023-06-20	88.981 mi
Registration #22	2024-06-20	88.981 mi
Registration #23	2025-06-20	88.981 mi
Registration #24	2026-06-20	88.981 mi
Registration #25	2027-06-20	88.981 mi
Registration #26	2028-06-20	88.981 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1740 mm
Length	4195 mm
Wheel base	2480 mm
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	RHWW4025018