




report date: 2024-03-28

General information

Make	MINI
Model	COOPER S AUTO JOHN COOPER WORKS
Colour	Black
Year of manufacture	2013
Top speed	148 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	211 BHP
Max. torque	260 Nm at 5.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G








Internet history

Entry 1

Date	2022-02-05
Pictures	61
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-28
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	2

MOT #13	2024-02-29 11:08
MOT test number	492107512665
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement rubber top mount starting to perish (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement rubber top mount splitting/advice replacement (5.3.4 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #12**

2024-02-22 09:23

MOT test number

779272875769

Result**✗ Failed**

- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Nearside Front Headlamp levelling device inoperative wiring loom broken off to sensor (4.1.5 (a))
- MAJOR** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement rubber top mount starting to perish (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement rubber top mount splitting/advise replacement (5.3.4 (a) (i))

MOT #11

2023-02-06 17:04

MOT test number

249896854168

Result**✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2022-01-25 16:05**MOT test number** 709849356768**Result** ✓ Passed**MOT #9** 2021-02-19 09:43**MOT test number** 634045092377**Result** ✓ Passed

Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #8 2021-02-19 09:43**MOT test number** 478163248896**Result** ✗ Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #7 2020-02-21 16:45**MOT test number** 643939422134**Result** ✓ Passed

Minor Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #6 2020-02-21 16:45**MOT test number** 977574033625**Result** ✗ Failed

Pass with rectification Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

Minor Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #5 2019-02-13 16:34**MOT test number** 950226385202**Result** ✓ Passed

**MOT #4** 2018-07-30 12:22**MOT test number** 351812601584**Result** ✓ Passed**MOT #3** 2018-07-29 13:45**MOT test number** 772295648952**Result** ✗ Failed

- MAJOR** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))
- MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #2 2017-08-12 14:23**MOT test number** 925393040328**Result** ✓ Passed**MOT #1** 2016-08-17 14:09**MOT test number** 427334486706**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
28 February 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-01
Last registration	2024-02-29
Complete history	See info



Registration #1	2013-09-01	12 mi
Registration #2	2016-08-17	28.971 mi
Registration #3	2017-08-12	42.194 mi
Registration #4	2018-07-29	50.202 mi
Registration #5	2018-07-30	50.228 mi
Registration #6	2019-02-13	55.492 mi
Registration #7	2020-02-21	69.375 mi
Registration #8	2020-02-21	69.375 mi
Registration #9	2020-02-21	69.375 mi
Registration #10	2020-02-21	69.375 mi
Registration #11	2020-02-21	69.375 mi
Registration #12	2020-02-21	69.375 mi
Registration #13	2020-02-21	69.375 mi
Registration #14	2020-02-21	69.375 mi
Registration #15	2020-02-21	69.375 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	A511J527
---------------	----------