



TOYOTA



report date: 2024-03-28

General information

|                     |                             |
|---------------------|-----------------------------|
| Make                | TOYOTA                      |
| Model               | COROLLA VERSO VVTI T SPIRIT |
| Colour              | Grey                        |
| Year of manufacture | -                           |
| Top speed           | 121 mph                     |
| 0 - 60 mph          | 10.8 seconds                |
| Gearbox             | 5 speed Manual              |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 127 BHP             |
| Max. torque             | 170 Nm at 4.200 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 28.5 mpg            |
| Consumption extra urban | 43.5 mpg            |
| Consumption combined    | 36.7 mpg            |



LABEL UNKNOWN



Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-10-19                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-10-18                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)

**MOT history**

|                         |  |
|-------------------------|--|
| <b>MOT #19</b>          | 2022-06-17 10:47   |
| <b>MOT test number</b>  | 229619688535   |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2023-06-25   |
| <b>Advice</b>           | Front bumper loose but not likely to become detached   |
| <b>Minor</b>            | Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))  |
| <b>Advice</b>           | Front Registration plate insecure but not likely to fall off (0.1 (a))   |
| <b>Minor</b>            | Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| <b>Advice</b>           | Front Registration plate deteriorated but not likely to be misread (0.1 (b))                                     |
| <b>Advice</b>           | Front Oil leak, but not excessive (8.4.1 (a) (i))  |
| <b>Advice</b>           | Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))                                      |
| <b>Minor</b>            | Offside Front Windscreen wiper blade defective wiper worn (3.4 (b) (i))  |

|                        |  |
|------------------------|--|
| <b>MOT #18</b>         | 2022-06-16 13:22   |
| <b>MOT test number</b> | 102059908574   |
| <b>Result</b>          | ✗ Failed   |
| <b>Advice</b>          | Front Oil leak, but not excessive (8.4.1 (a) (i))  |
| <b>Minor</b>           | Offside Front Windscreen wiper blade defective wiper worn (3.4 (b) (i))  |
| <b>Fail</b>            | Offside Front Position lamp not working (4.2.1 (a) (ii))   |
| <b>Advice</b>          | Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))                                      |
| <b>Minor</b>           | Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))  |
| <b>Advice</b>          | Front Registration plate insecure but not likely to fall off (0.1 (a))   |
| <b>Advice</b>          | Front bumper loose but not likely to become detached   |
| <b>Fail</b>            | Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))  |
| <b>Minor</b>           | Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| <b>Advice</b>          | Front Registration plate deteriorated but not likely to be misread (0.1 (b))                                     |

**MOT #17** 2021-06-23 09:38**MOT test number** 894412032005**Result** ✓ Passed**MOT #16** 2021-06-23 09:37**MOT test number** 129135716610**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2020-06-26 12:01**MOT test number** 379930433308**Result** ✓ Passed**Advice** Suspension component mounting prescribed area is corroded but not considered excessive nearside rear and offside rear (5.3.6 (a) (i))**Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security nearside rear and offside rear inner sill sections (6.2.2 (d) (i))**MOT #14** 2019-06-13 09:54**MOT test number** 863893831456**Result** ✓ Passed**Advice** Under body has surface corrosion front to back both sides**MOT #13** 2018-06-18 16:04**MOT test number** 192997504352**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #12** 2017-06-20 11:10**MOT test number** 406601929452**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Play in steering rack inner joint(s)**MOT #11** 2016-12-21 17:29**MOT test number** 305847087035**Result** ✓ Passed**MOT #10** 2016-04-13 07:39**MOT test number** 902926971083**Result** ✓ Passed**Advice** Sill covers fitted**Advice** Nearside front shocker leaking**Advice** Nearside rear tyre outer edge worn**MOT #9** 2015-04-28 09:18**MOT test number** 289328715407**Result** ✓ Passed**Notice** Wiper blades split**Notice** Rear brake pads worn**Notice** Nearside front shock absorber leaking**Notice** Rear most seats folded away**Notice** Sill covers fitted**Notice** Nearside rear tyre worn low

**MOT #8** 2014-04-30 09:15**MOT test number** 247820324187**Result** ✓ Passed

- Notice** Sill covers fitted
- Notice** Rear most seats folded away
- Notice** Under-trays fitted obscuring some underside components

**MOT #7** 2013-04-10 09:05**MOT test number** 627660303151**Result** ✓ Passed

- Notice** Sill covers and under trays fitted.
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-04-11 09:59**MOT test number** 428822102160**Result** ✓ Passed**MOT #5** 2011-04-20 11:00**MOT test number** 895170211185**Result** ✓ Passed**MOT #4** 2010-04-26 12:09**MOT test number** 211426410407**Result** ✓ Passed**MOT #3** 2009-05-05 16:44**MOT test number** 884095229115**Result** ✓ Passed



|                 |   |
|-----------------|---|
| MOT #2          | 2009-03-05 14:35  |
| MOT test number | 582984869047  |
| Result          | ✓ Passed  |
| Advice          | Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |
| Advice          | Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)  |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2008-04-22 10:17 |
| MOT test number | 150253818111     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 22                       |
| First mileage registration | 2005-04-29               |
| Last registration          | 2022-06-17               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2005-04-29 | 24 mi      |
| Registration #2  | 2008-04-22 | 22.336 mi  |
| Registration #3  | 2009-03-05 | 31.035 mi  |
| Registration #4  | 2009-05-05 | 28.312 mi  |
| Registration #5  | 2010-04-26 | 33.455 mi  |
| Registration #6  | 2011-04-20 | 37.896 mi  |
| Registration #7  | 2012-04-11 | 43.560 mi  |
| Registration #8  | 2013-04-10 | 49.947 mi  |
| Registration #9  | 2014-04-30 | 54.264 mi  |
| Registration #10 | 2015-04-28 | 59.386 mi  |
| Registration #11 | 2016-04-13 | 64.804 mi  |
| Registration #12 | 2017-04-20 | 70.222 mi  |
| Registration #13 | 2018-04-19 | 75.640 mi  |
| Registration #14 | 2019-04-18 | 81.058 mi  |
| Registration #15 | 2020-04-17 | 86.476 mi  |
| Registration #16 | 2021-04-16 | 91.894 mi  |
| Registration #17 | 2022-04-15 | 97.312 mi  |
| Registration #18 | 2023-04-14 | 102.730 mi |
| Registration #19 | 2024-04-13 | 108.148 mi |
| Registration #20 | 2025-04-12 | 113.566 mi |
| Registration #21 | 2026-04-11 | 118.984 mi |
| Registration #22 | 2027-04-10 | 124.402 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1770 mm |
| Height              | 1660 mm |
| Length              | 4360 mm |
| Wheel base          | 2750 mm |
| Kerb weight         | 1365 kg |
| Max. allowed weight | 2035 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 7                     |

|                        |            |
|------------------------|------------|
| <b>Number of axles</b> | 2          |
| <b>Engine number</b>   | 1ZZE316584 |