





General information

| Make | HONDA |
|---------------------|------------------------|
| Model | CIVIC I-DTEC SR TOURER |
| Colour | Grey |
| Year of manufacture | 2016 |
| Top speed | 121 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 2.000 rpm |
| Engine capacity | 1.597 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 65.7 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 72.4 mpg |
| CO2 emission | 103 g/km |
| CO2 label | В |





Internet history

| Entry | 1 |
|-------|---|
| Date | |

Pictures

2021-01-31

10

Listing price

View report



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-03-25 |
|--------------------|------------|
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 3 |

| МОТ #9 | 2024-03-23 10:56 |
|------------------|------------------|
| MOT test number | 597834942766 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-25 |

| MOT #8 | 2023-03-10 13:24 |
|-----------------|------------------|
| MOT test number | 846985624808 |
| Result | ✓ Passed |

| MOT #7 | 2022-03-21 16:55 |
|-----------------|------------------|
| MOT test number | 266304213308 |
| Result | ✓ Passed |

| МОТ #6 | 2021-03-26 16:46 |
|-----------------|------------------|
| MOT test number | 970479265223 |
| Result | ✓ Passed |





| MOT #5 | 2020-08-05 08:08 | |
|---|------------------|--|
| MOT test number | 404450463480 | |
| Result | ✓ Passed | |
| Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) | | |
| Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | | |

| МОТ #4 | 2019-08-06 10:56 |
|-----------------|------------------|
| MOT test number | 164508105846 |
| Result | ✓ Passed |
| | |

| MOT #3 | 2019-08-06 10:56 |
|-------------------------------------|--|
| MOT test number | 288720985942 |
| Result | × Failed |
| Pass with rectification (h)) | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 |

| MOT #2 | 2019-03-28 09:53 |
|-----------------|------------------|
| MOT test number | 213185138965 |
| Result | ✓ Passed |

| MOT #1 | 2019-03-28 09:53 |
|-------------------------|---|
| MOT test number | 701449025826 |
| Result | × Failed |
| Pass with rectification | Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a)) |
| Pass with rectification | Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a)) |



Tax & MOT check

| ✓ Taxed Tax due: 1 February 2025 | ✓ MOT Expires: 25 March 2025 |
|---|---------------------------------------|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 25 March 2025 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---|-------|
| Date | F | |
| Category | | LAMP |
| Туре | | |
| Damage 2 | | XAMPL |
| Date | | |
| Category | | SN61 |
| Туре | | |

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HONDA had different number pla | tes. |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-05-25 |
| Last registration | 2024-03-23 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-05-25 | 7 mi |
|------------------|------------|------------|
| Registration #2 | 2019-03-28 | 22.379 mi |
| Registration #3 | 2019-03-28 | 22.379 mi |
| Registration #4 | 2019-08-06 | 24.550 mi |
| Registration #5 | 2019-08-06 | 24.550 mi |
| Registration #6 | 2020-08-05 | 59.006 mi |
| Registration #7 | | 11.117 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 mi |
| Registration #11 | | 11.777 mi |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 83% |
| Pedestrian | 69% |
| Safety systems | 86% |
| Overall rating | 86% |
| Video | see crash video |



| Dimensions & weight | |
|---|-----------------------|
| Width | 1770 mm |
| Height | 1480 mm |
| Length | 4590 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1440 kg |
| Max. allowed weight | 1910 kg |
| | |
| Additional information | |
| Additional information Fuel delivery | Direct Injection |
| | Direct Injection 5 |
| Fuel delivery | |
| Fuel delivery Number of doors | 5 |
| Fuel delivery Number of doors Number of seats | 5 |