





report date: 2024-03-28

General information

Make	FIAT
Model	500C POP DUALOGIC
Colour	White
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date	2021-08-06
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-08-16
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	19
Total items failed	15

MOT #16	2023-08-14 14:58
MOT test number	296951953386
Result	✓ Passed
Next expiry date	2024-08-16

MOT #15	2022-08-11 12:56
MOT test number	928567939060
Result	✓ Passed
Advice Oil leak gearbox	

MOT #14	2022-08-10 11:11
MOT test number	177158973132
Result	X Failed
Advice Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Oil leak gearbox	

MOT #13	2021-08-17 11:05
MOT test number	146159172495
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #12 2020-10-15 16:02

MOT test number 753223333777

MOT #11 2020-10-15 16:02

MOT test number 559422945973

Result × Failed

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #10 2019-10-24 13:32

MOT test number 536594287241

Result \rightarrow Passed

Advice Offside Front suspension top mount has slight play

Advice Exhaust back box outer skin peeling off

Advice Both front tyres are wearing on the inner edge

MOT #9 2018-10-17 15:03

MOT test number 253524568989

Result

Passed

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e))

Advice Exhaust rear silencer corroded

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Backbox outer skin corroded

MOT #7 2017-09-26 08:44 **MOT** test number 450863080215 Result × Failed **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) **Advice** Backbox outer skin corroded Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6	2016-10-17 13:00
MOT test number	396799625776
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #5 2016-10-17 10:10

MOT test number 794464283115

Result X Failed

Fail Registration plate lamp not working both sides (1.1.C.1d)

Advice OS driving light not working

Fail Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)

Fail Windscreen wiper does not clear the windscreen effectively both front (8.2.2)

Fail Headlamp aim too low both sides (1.8)

Fail Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #4 2015-10-20 16:05

MOT test number 829846541133

Result ✓ Passed

Advice Tailgate not opening on exterior handle.

MOT #3 2015-10-20 11:37

MOT test number 843447375423

Result ★ Failed

Fail Windscreen wiper does not clear the windscreen effectively OS and NS front. (8.2.2)

Advice Front tyres scrubbing on edges, and splitting around tread pattern

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Tailgate not opening on exterior handle.

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2	2014-10-17 17:00
MOT test number	877250394254
Result	✓ Passed
MOT #1	2013-09-24 09:37
MOT test number	535647263212

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	UK NIEZ	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



WN61NWV

report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-30
Last registration	2023-08-14
Complete history	See info



Registration #1	2011-09-30	18 mi
Registration #2	2013-09-24	9.617 mi
Registration #3	2014-10-17	16.112 mi
Registration #4	2015-10-20	24.688 mi
Registration #5	2015-10-20	24.688 mi
Registration #6	2016-10-17	33.736 mi
Registration #7	2016-10-17	33.736 mi
Registration #8	2017-09-26	42.231 mi
Registration #9	2017-09-26	42.231 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I	
Fuel delivery	Multi-Point Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page	e 14/14

Number of axles 2

Engine number 6491843