





General information

Make	FIAT
Model	TIPO EASY PLUS
Colour	Silver
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





wrand take: 2024-03-29

Internet history Entry 1 Date 2022-04-27 Pictures 12 Listing price View report MOTOR PLUS MOTOR PLUS **MOTOR PLUS** Covid-19 Secure We are committed to keeping our customers safe: 2 result damming Programmers in plane Programmers in plane Programmers in plane Stafe arms, internal, it tradewr Stafe arms, internal, it tradewr Stafe arms, internal, it tradewr Stafe arms, unther To build your deal on this vehicle Visit our website and click the reserve button Video viewing Book a video viewing with one of our team. See the vehicle from the comfort of your own home. AWAITING PHOTOS Visit our website for more into source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #6	2023-05-18 11:52
MOT test number	618975993151
Result	✓ Passed
Next expiry date	2024-05-18

MOT #5	2022-05-19 12:11
MOT test number	238345841866
Result	✓ Passed

MOT #4	2022-05-18 11:46
MOT test number	854484847495
Result	🗙 Failed
Fail Rear Shock absorbers has a serious fluid leak both (5.3.2 (b)) Fail Rear Shock absorbers has a serious fluid leak both (5.3.2 (b))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	



W	R6	7 V	V	F	0
	report	date:	202	4-0	3-29

MOT #3		2021-11-15 14:52	
MOT test	number	446139088353	
Result		✓ Passed	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Nearside Rear Tyre slightly damaged/cracking or perishing inner and outer walls (5.2.3 (d) (ii))		
Advice	Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge outer tread 2.5mm (5.2.3 (e))			
MOT #2		2021-11-15 12:11	
MOT test	number	219611116196	
Result		🗙 Failed	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing inner and outer v	valls (5.2.3 (d) (ii))	

Nearside Front Tyre worn close to legal limit/worn on edge outer tread 2.5mm (5.2.3 (e))

Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 MOT test number

Advice

Advice

Fail

Result

2020-10-07 13:26

699044378820

🗸 Passed



Tax & MOT check

√ Taxed	√ мот
Tax due: 1 September 2024	Expires: 18 May 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	UK
Plate since Current registration	
Plate since Carrent registration Plate since	1000-20-20





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-10-31
Last registration	2023-05-18
Complete history	<u>See info</u>



Registration #1	2017-10-31	21 mi
Registration #2	2020-10-07	28.361 mi
Registration #3	2021-11-15	34.619 mi
Registration #4	2021-11-15	34.624 mi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		10.300 est





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	2245020