





report date: 2024-03-28

General information

Make	AUDI
Model	Q5 TDI QUATTRO S LINE PLUS
Colour	Silver
Year of manufacture	2015
Top speed	130 mph
0 - 100 km/h	8.4 seconds
0 - 60 mph	8.4 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 187 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/12



EO65XVZ

report date: 2024-03-28


Internet history

Entry 2

Date 2021-09-20

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-09-18

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	20
Total items failed	0

MOT #9	2023-11-21 15:11
MOT test number	637859208114
Result	✓ Passed
Next expiry date	2024-11-20
Minor Offside Rear reflector defective or damaged by up to 50% of the ref	flecting surface (4.8.1 (a) (i))

MOT #8	2022-09-27 12:11
MOT test number	307098498343
Result	✓ Passed
MOT #7	2021-09-18 14:58
MOT test number	524442825972
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #6 2020-09-26 08:44

MOT test number 531291819753

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre 3.0mm and wearing flat spots at inner edge. (5.2.3 (e))

Advice NSR tyre punctured

Advice Front Brake disc worn, but not excessively discs are lipped with wear (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre 3.0mm (5.2.3 (e))

Advice Rear Brake disc worn, but not excessively discs lipped with wear (1.1.14 (a) (i))

MOT #5 2020-09-25 11:17

MOT test number 886093858407

Result X Failed

Advice Front Brake disc worn, but not excessively discs are lipped with wear (1.1.14 (a) (i))

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick outer pad (1.1.13 (a) (ii))

MAJOR Nearside Front Brake pad(s) worn down to wear indicator inner pad (1.1.13 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre 3.0mm (5.2.3 (e))

Advice NSR tyre punctured

Advice Rear Brake disc worn, but not excessively discs lipped with wear (1.1.14 (a) (i))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick inner pad (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre 3.0mm and wearing flat spots at inner edge. (5.2.3 (e))

MOT #4 2019-09-21 12:01

MOT test number 995854009265

Advice Both front brake discs are wearing a lip.

CarCheck.co.uk page 4/12



Result

(d) (i))

EO65XVZ

report date: 2024-03-28

× Failed

MOT test number

Result

MAJOR

Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

Advice

Both front brake discs are wearing a lip.

MAJOR

Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MAJOR

Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #2

MOT test number

Fesult

MOT #1

2018-08-30 13:14

518294990034

✓ Passed

✓ Passed

MOT #1

304586942959

MAJOR Nearside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra AUDI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



EO65XVZ

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union mestery	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NIA.
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-28
Last registration	2023-11-21
Complete history	See info



Registration #1	2015-09-28	18 mi
Registration #2	2018-08-29	46.704 mi
Registration #3	2018-08-30	46.770 mi
Registration #4	2019-09-21	61.067 mi
Registration #5	2019-09-21	61.071 mi
Registration #6	2020-09-25	75.731 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



EO65XVZ

report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	32%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1898 mm
Height	1655 mm
Length	4629 mm
Wheel base	2807 mm
Kerb weight	1860 kg
Max. allowed weight	2470 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

Engine number CNHA172332