



report date: 2024-03-29

General information

| | |
|---------------------|-----------------|
| Make | VOLKSWAGEN |
| Model | GOLF GT TDI 140 |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 127 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 320 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 39.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 49.6 mpg |



LABEL UNKNOWN

**MOT history**

| | |
|-------------------------|------------------|
| MOT #15 | 2022-01-26 09:27 |
| MOT test number | 801847997061 |
| Result | ✓ Passed |
| Next expiry date | 2023-01-25 |

| | |
|------------------------|------------------|
| MOT #14 | 2022-01-26 09:27 |
| MOT test number | 129185428046 |
| Result | ✗ Failed |

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

| | |
|------------------------|------------------|
| MOT #13 | 2021-01-20 08:48 |
| MOT test number | 401622517053 |
| Result | ✓ Passed |

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

| | |
|------------------------|------------------|
| MOT #12 | 2019-04-30 14:25 |
| MOT test number | 737198737226 |
| Result | ✓ Passed |

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11** 2018-05-02 14:27**MOT test number** 924878786328**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2018-05-02 14:27**MOT test number** 728140816713**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-06-10 07:29**MOT test number** 805168177333**Result** ✓ Passed

**MOT #8** 2016-06-07 11:34**MOT test number** 416707435672**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Oil leak
- Advice** Undertrays
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Engine cover

MOT #7 2016-06-04 10:12**MOT test number** 122058328405**Result** ✗ Failed

- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Oil leak
- Advice** Undertrays
- Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Engine cover

MOT #6 2015-03-11 10:43**MOT test number** 737200375080**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #5** 2015-03-11 09:23**MOT test number** 435660175021**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #4** 2014-03-10 13:39**MOT test number** 827759364021**Result** ✓ Passed**MOT #3** 2013-02-27 11:48**MOT test number** 707878153035**Result** ✓ Passed**MOT #2** 2012-03-23 09:38**MOT test number** 558943082002**Result** ✓ Passed**MOT #1** 2011-05-20 11:51**MOT test number** 236410341457**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  LN08EFB |
| Plate since | 2024-03-29 |
| Current registration |  LN08EFB |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2008-06-09 |
| Last registration | 2022-01-26 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-06-09 | 13 mi |
| Registration #2 | 2011-05-20 | 55.746 mi |
| Registration #3 | 2012-03-23 | 74.122 mi |
| Registration #4 | 2013-02-27 | 96.507 mi |
| Registration #5 | 2014-03-10 | 123.042 mi |
| Registration #6 | 2015-03-11 | 142.964 mi |
| Registration #7 | 2015-03-11 | 142.964 mi |
| Registration #8 | 2016-06-04 | 153.000 mi |
| Registration #9 | 2016-06-04 | 153.000 mi |
| Registration #10 | 2016-06-04 | 153.000 mi |
| Registration #11 | 2016-06-04 | 153.000 mi |
| Registration #12 | 2016-06-04 | 153.000 mi |
| Registration #13 | 2016-06-04 | 153.000 mi |
| Registration #14 | 2016-06-04 | 153.000 mi |
| Registration #15 | 2016-06-04 | 153.000 mi |
| Registration #16 | 2016-06-04 | 153.000 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1759 mm |
| Height | 1479 mm |
| Length | 4204 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1299 kg |
| Max. allowed weight | 1910 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | BKD C72022 |