



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D5 ES
Colour	Blue
Year of manufacture	2011
Top speed	143 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 2


Date	2022-01-23
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-23
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-20
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	4
Total items failed	2

MOT #12	2023-09-20 08:24
MOT test number	553957916457
Result	✓ Passed
Next expiry date	2024-09-20

MOT #11	2023-09-19 08:13
MOT test number	197993212832
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10	2022-09-21 12:34
MOT test number	345741014946
Result	✓ Passed

MOT #9	2022-09-20 13:02
MOT test number	124239852006
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #8** 2021-09-15 09:34**MOT test number** 435037262200**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on outer circumference (5.2.3 (e))**MOT #7** 2020-09-16 13:36**MOT test number** 607444584738**Result** ✓ Passed**MOT #6** 2019-11-13 11:07**MOT test number** 957578305465**Result** ✓ Passed**MOT #5** 2018-11-16 13:47**MOT test number** 538628017565**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2017-11-17 13:20**MOT test number** 661909173134**Result** ✓ Passed**MOT #3** 2016-10-10 15:24**MOT test number** 829277239562**Result** ✓ Passed



MOT #2	2015-11-02 15:42
MOT test number	462774216685
Result	✓ Passed

MOT #1	2014-11-03 14:28
MOT test number	517307604397
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 September 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK61XDJ
Plate since	2024-03-28
Current registration	AK61XDJ
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-30
Last registration	2023-09-20
Complete history	See info



Registration #1	2011-11-30	7 mi
Registration #2	2014-11-03	29.717 mi
Registration #3	2015-11-02	40.177 mi
Registration #4	2016-10-10	47.301 mi
Registration #5	2017-11-17	61.715 mi
Registration #6	2018-11-16	69.204 mi
Registration #7	2019-11-13	81.587 mi
Registration #8	2020-09-16	87.940 mi
Registration #9	2020-09-16	87.940 mi
Registration #10	2020-09-16	87.940 mi
Registration #11	2020-09-16	87.940 mi
Registration #12	2020-09-16	87.940 mi
Registration #13	2020-09-16	87.940 mi
Registration #14	2020-09-16	87.940 mi
Registration #15	2020-09-16	87.940 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1613 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1006321